

REF:

LPC / 220015771KV

ASSIGNMENT

Pm 9000h Yr Regn:

12, 13

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

K. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 32222

Your Reference : Z21VP05029372

Accident Date : 16-Feb-2022

Date : 18-Feb-2022

Our Ref : 021645 / SANDRA

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

NOT Authorize PAGE : 1
C1 Pm 83700h
Pm 83700h
Ex 8500h 6days

ESTIMATED COST OF REPAIR FOR TOYOTA FORTUNER 2WD (2694CC)(2013) SML9008C

1 pc front bumper		CM 240.00 c	✓
2 pcs front bumper side retainer (LH&RH)	@ S\$ 35.00	CM 70.00 c	✓
10 pcs front bumper clips	@ S\$ 1.50	CM 15.00 c	✓
1 pc RH front bumper foglamp		CM 135.00 c	✓
1 pc RH front bumper foglamp cover		MR 55.00 c	✓
1 pc front bumper lower centre grille		MR 130.00 c	✓
1 pc RH front bumper side mounting bracket		SL 35.00 c	✓
1 pc RH front bumper retainer bracket		SL 40.00 c	✓
1 pc front bumper reinforcement		R 120.00 c	✓
1 pc RH front bumper reinforcement bracket		R 35.00 c	✓
1 pc front grille		SL 295.00 c	X
1 pc front grille bracket		R 200.00 c	X
10 pcs front grille clips	@ S\$ 1.50	MR 15.00 c	X
1 pc front grille logo		MR 55.00 c	X
1 pc front grille top seal		SL 45.00 c	X
1 pc RH front fender		MR 195.00 c	✓
1 pc RH front fender inner shield		CM 145.00 c	✓
10 pcs RH front fender inner shield clips	@ S\$ 1.50	MR 15.00 c	✓
1 pc RH front fender wheel arch garnish		MR 200.00 c	✓
1 pc RH front fender wheel arch garnish top moulding			no stock SL X

Con't Page 2 ...

REF:

LPC / 220015771KV

ASSIGNMENT

key to continue.

K. Kim HinCO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sgYour Reference : Z21VP05029372
Our Ref : 021645Page : 2
No. : 32222

1 pc	RH headlamp panel and front support panel	B	295.00	c	✓
1 pc	front bumper under cover	Sm	150.00	c	X
10 pcs	front bumper under cover clips @ S\$ 1.50	m	15.00	c	X
1 pc	RH headlamp	CM	350.00	c	✓
1 pc	air pump	Sm	750.00	c	X
1 pc	air pump bracket	n	135.00	c	X
1 pc	air pump cover	Sm	115.00	c	X
1 pc	RH front shock absorber	B	125.00	c	X
1 pc	RH front shock absorber mounting	Sm	85.00	c	X
1 pc	RH front stabilizer bar linkage	Sm	95.00	c	X
1 pc	RH front upper arm	Sm	320.00	c	X
1 pc	RH front knuckle arm	B	300.00	c	X
1 pc	RH front lower arm	Di's	310.00	c	X
1 pc	RH front lower arm balljoint attachment	B	75.00	c	X
1 pc	RH front tie rod	Sm	125.00	c	X
1 pc	RH front tie rod end	Sm	130.00	c	X
			5,415.00		
Add 15% :			812.25		
			6,227.25		

1 pc RH front tyre
1 pc RH front rimSm 260.00 sn X
Sm 450.00 sn XTo remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00

To remove aircon condenser, pipes
and driers, Vaccum and recharge gas

100.00

To dismantle and check front under-
carriages. To replace affected
portions.

180.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 3 ...

REF: *LPC / 220015771KV*

key to continue...

K. Kim Hin
AUTO PTE LTD

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 3
No. : 32222

To conduct front wheel alignment test.	80.00	<i>601</i>
To putty and respray on affected portions.	800.00	<i>7001</i>
To focus headlamps. To check front wiring and lighting operation.	30.00	<i>201</i>
Total :	S\$ 8,927.25	

Singapore Dollars EIGHT THOUSAND NINE HUNDRED
TWENTY SEVEN AND CENTS TWENTY FIVE Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.