

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 32222

Your Reference : Z21VP05029372
Accident Date : 16-Feb-2022

Date : 18-Feb-2022

Our Ref : 021645 / SANDRA

Not Authorized PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

*U/Pm &
Penny After Paint*

Ex @ 500k 6 days

ESTIMATED COST OF REPAIR FOR TOYOTA FORTUNER 2WD (2694CC)(2013) SML9008C

1 pc	front bumper		CM 240.00 c ✓
2 pcs	front bumper side retainer (LH&RH)	@ S\$ 35.00	CM 70.00 c ✓
10 pcs	front bumper clips	@ S\$ 1.50	M 15.00 c ✓
1 pc	RH front bumper foglamp		CM 135.00 c ✓
1 pc	RH front bumper foglamp cover		M 55.00 c ✓
1 pc	front bumper lower centre grille		Red 130.00 c ✓
1 pc	RH front bumper side mounting bracket		35.00 c 7
1 pc	RH front bumper retainer bracket		40.00 c 7
1 pc	front bumper reinforcement		120.00 c 7
1 pc	RH front bumper reinforcement bracket		35.00 c 7
1 pc	front grille		Sn 295.00 c X
1 pc	front grille bracket		R 200.00 c X
10 pcs	front grille clips	@ S\$ 1.50	RV 15.00 c X
1 pc	front grille logo		RV 55.00 c X
1 pc	front grille top seal		Sn 45.00 c X
1 pc	RH front fender		B 195.00 c ✓
1 pc	RH front fender inner shield		CM 145.00 c ✓
10 pcs	RH front fender inner shield clips	@ S\$ 1.50	M 15.00 c ✓
1 pc	RH front fender wheel arch garnish		B 200.00 c ✓
1 pc	RH front fender wheel arch garnish top moulding		

*no stock
?*

y key to continue.

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

K. Kim Hin

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 2
No. : 32222

1 pc	RH headlamp panel and front support panel	B	295.00	c	✓
1 pc	front bumper under cover		150.00	c	7
10 pcs	front bumper under cover clips @ S\$ 1.50		15.00	c	7
1 pc	RH headlamp	cm	350.00	c	✓
1 pc	air pump		750.00	c	7
1 pc	air pump bracket		135.00	c	7
1 pc	air pump cover		115.00	c	7
1 pc	RH front shock absorber		125.00	c	7
1 pc	RH front shock absorber mounting	h	85.00	c	X
1 pc	RH front stabilizer bar linkage	h	95.00	c	X
1 pc	RH front upper arm		320.00	c	7
1 pc	RH front knuckle arm	h	300.00	c	X
1 pc	RH front lower arm		310.00	c	7
1 pc	RH front lower arm balljoint attachment	h	75.00	c	X
1 pc	RH front tie rod	h	125.00	c	X
1 pc	RH front tie rod end	h	130.00	c	X

Add 15% : 5,415.00
812.25

6,227.25

1 pc RH front tyre
1 pc RH front rim

h 260.00 sn X
h 450.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00 *600*

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

100.00 ✓

To dismantle and check front under-
carriages. To replace affected
portions.

180.00 7

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Con: Page 3 ...

Acknowledged by Repairer

Signature:

Date:

key to continue.

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

K. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 3
No. : 32222

To conduct front wheel alignment
test.

80.00 601

To putty and respray on affected
portions.

800.00 7001

To focus headlamps. To check front
wiring and lighting operation.

30.00 201

Total : S\$ 8,927.25

Singapore Dollars EIGHT THOUSAND NINE HUNDRED
TWENTY SEVEN AND CENTS TWENTY FIVE Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.