

**K. Kim Hin**CO. REG. NO: 199402370D
GST NO: M2-0123250-3**AUTO PTE LTD****金興(龔)汽車私人有限公司**160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sgYour Reference : Z21VP05029372
Accident Date : 16-Feb-2022Limit
\$6000/-

No. : 32222

Date : 18-Feb-2022

Our Ref : 021645 / SANDRA

NOT Authorised PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555C/Pay @
Repair After Paint

Ex @ 500k

6 days

ESTIMATED COST OF REPAIR FOR TOYOTA FORTUNER 2WD (2694CC)(2013) SML9008C

1 pc	front bumper		CM	240.00	c	✓
2 pcs	front bumper side retainer (LH&RH)	@ S\$ 35.00	CM	70.00	c	✓ 35
10 pcs	front bumper clips	@ S\$ 1.50	CM	15.00	c	✓
1 pc	RH front bumper foglamp		CM	135.00	c	✓
1 pc	RH front bumper foglamp cover		CM	55.00	c	✓
1 pc	front bumper lower centre grille		CM	130.00	c	✓
1 pc	RH front bumper side mounting bracket			35.00	c	7 X
1 pc	RH front bumper retainer bracket			40.00	c	7 X
1 pc	front bumper reinforcement			120.00	c	7 X
1 pc	RH front bumper reinforcement bracket			35.00	c	7 X
1 pc	front grille		SM	295.00	c	X
1 pc	front grille bracket		R	200.00	c	X
10 pcs	front grille clips	@ S\$ 1.50	SM	15.00	c	X
1 pc	front grille logo		SM	55.00	c	X
1 pc	front grille top seal		SM	45.00	c	X
1 pc	RH front fender		SM	195.00	c	✓
1 pc	RH front fender inner shield		CM	145.00	c	✓
10 pcs	RH front fender inner shield clips	@ S\$ 1.50	SM	15.00	c	✓
1 pc	RH front fender wheel arch garnish		SM	200.00	c	✓
1 pc	RH front fender wheel arch garnish top moulding					X

no stock
?

Key to continue...

K. Kim Hin

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 2
No. : 32222

1 pc RH headlamp panel and front support panel	Bz	295.00	c	✓
1 pc front bumper under cover		150.00	c	7X
10 pcs front bumper under cover clips @ S\$ 1.50		15.00	c	7X
1 pc RH headlamp	cm	350.00	c	✓
1 pc air pump		750.00	c	7X
1 pc air pump bracket		135.00	c	7X
1 pc air pump cover		115.00	c	7X
1 pc RH front shock absorber		125.00	c	7✓
1 pc RH front shock absorber mounting	h	85.00	c	X
1 pc RH front stabilizer bar linkage	h	95.00	c	X
1 pc RH front upper arm		320.00	c	7X
1 pc RH front knuckle arm	h	300.00	c	X✓
1 pc RH front lower arm		310.00	c	7✓
1 pc RH front lower arm balljoint attachment	h	75.00	c	X✓
1 pc RH front tie rod	h	125.00	c	X
1 pc RH front tie rod end	h	130.00	c	X

Add 15% : 5,415.00
812.25

6,227.25

1 pc RH front tyre
1 pc RH front rim

h 260.00 sn X
h 450.00 sn X

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

800.00

To remove aircon condenser, pipes
and driers. Vaccum and recharge gas

100.00 ✓

To dismantle and check front under-
carriages. To replace affected
portions.

180.00 7✓

150

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Con' Page 3 ...

key to continue.



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 3
No. : 32222

To conduct front wheel alignment
test.

80.00 601

To putty and respray on affected
portions.

800.00 7001

To focus headlamps. To check front
wiring and lighting operation.

30.00 201

Total : S\$ 8,927.25

Singapore Dollars EIGHT THOUSAND NINE HUNDRED
TWENTY SEVEN AND CENTS TWENTY FIVE Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

2620.00
+ 15%

3013.00
+ 1630.00

4643.00
- 20%

3714.40

2/Sum \$3700/-