

ASS. REC. BY:

REF:

LPC /

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: \$36k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV 1 REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMZ 9008C

Yr Regn:

12, 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Fortuner V

c.c

2694

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

121059

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

M4FZ X69G.807058911

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / Rlm or

Tyre Size:

F:

R:

265/65R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

S + RS. SI

Fines

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkimhin.com.sg

No. : 32222

Your Reference : Z21VP05029372
Accident Date : 16-Feb-2022

Date : 18-Feb-2022

Our Ref : 021645 / SANDRA

Not Authorised PAGE : 1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
Singapore 199555

*61 Pym &
Penny After Paint*

Ex @ 500p

6 days

ESTIMATED COST OF REPAIR FOR TOYOTA FORTUNER 2WD (2694CC)(2013) SML9008C

1 pc	front bumper		CM	240.00	c	✓
2 pcs	front bumper side retainer (LH&RH)	@ S\$ 35.00	CM	70.00	c	✓
10 pcs	front bumper clips	@ S\$ 1.50	M	15.00	c	✓
1 pc	RH front bumper foglamp		CM	135.00	c	✓
1 pc	RH front bumper foglamp cover		Mrs	55.00	c	✓
1 pc	front bumper lower centre grille		Red	130.00	c	✓
1 pc	RH front bumper side mounting bracket			35.00	c	7
1 pc	RH front bumper retainer bracket			40.00	c	7
1 pc	front bumper reinforcement			120.00	c	7
1 pc	RH front bumper reinforcement bracket			35.00	c	7
1 pc	front grille		Sn	295.00	c	X
1 pc	front grille bracket		R	200.00	c	X
10 pcs	front grille clips	@ S\$ 1.50	nm	15.00	c	X
1 pc	front grille logo		nm	55.00	c	X
1 pc	front grille top seal		Sn	45.00	c	X
1 pc	RH front fender		Bj	195.00	c	✓
1 pc	RH front fender inner shield		CM	145.00	c	✓
10 pcs	RH front fender inner shield clips	@ S\$ 1.50	M	15.00	c	✓
1 pc	RH front fender wheel arch garnish		Bu	200.00	c	✓
1 pc	RH front fender wheel arch garnish top moulding					

*no stock
?*

y key to continue.

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

K. Kim Hin

AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 2
No. : 32222

1 pc	RH headlamp panel and front support panel	B	295.00	c	✓
1 pc	front bumper under cover		150.00	c	7
10 pcs	front bumper under cover clips @ S\$ 1.50		15.00	c	7
1 pc	RH headlamp	cm	350.00	c	✓
1 pc	air pump		750.00	c	7
1 pc	air pump bracket		135.00	c	7
1 pc	air pump cover		115.00	c	7
1 pc	RH front shock absorber		125.00	c	7
1 pc	RH front shock absorber mounting	h	85.00	c	X
1 pc	RH front stabilizer bar linkage	h	95.00	c	X
1 pc	RH front upper arm		320.00	c	7
1 pc	RH front knuckle arm	h	300.00	c	X
1 pc	RH front lower arm		310.00	c	7
1 pc	RH front lower arm balljoint attachment	h	75.00	c	X
1 pc	RH front tie rod	h	125.00	c	X
1 pc	RH front tie rod end	h	130.00	c	X

5,415.00

Add 15% : 812.25

6,227.25

- 1 pc RH front tyre
- 1 pc RH front rim

h 260.00 sn X
h 450.00 sn X

To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.

800.00

To remove aircon condenser, pipes and driers. Vaccum and recharge gas

100.00

To dismantle and check front under-carriages. To replace affected portions.

180.00 7

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Con't Page 3 ...

Acknowledged by Repairer

Signature:

Date:

key to continue.

CO. REG. NO: 199402370D
GST NO: M2-0123250-3

K. Kim Hin AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-20,
Sin Ming AutoCity, Singapore 575722
Tel: 6452 7018 Fax: 6458 3895
Email: service@kkinhin.com.sg

Your Reference : Z21VP05029372
Our Ref : 021645

Page : 3
No. : 32222

To conduct front wheel alignment
test.

80.00 *601*

To putty and respray on affected
portions.

800.00 *7001*

To focus headlamps. To check front
wiring and lighting operation.

30.00 *201*

Total : S\$ 8,927.25

Singapore Dollars EIGHT THOUSAND NINE HUNDRED
TWENTY SEVEN AND CENTS TWENTY FIVE Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission
Date of Accident 16/02/2022 20:43 (SGT)
Exact Location of Accident 16/02/2022 11:15 (SGT)
Additional Location Information Singapore
Country/State of Loss PORTSDOWN FLYOVER TWDS ALEXANDRA
Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SML9008C

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner TAN CHENG HOE
NRIC No SXXXX170B
Email Address TAN.CHENGHOE1127@GMAIL.COM
Mobile Phone No (Phone) +65-98291127
Alternative Phone No +65-98291127

VEHICLE PARTICULARS

Manufacturer Toyota
Model Fortuner
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 2694

INSURANCE COMPANY

Name of Insurance Company Lonpac Insurance Bhd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number Z21VP05029372
Cover Note Number -

DRIVER

Name of Driver TAN CHENG HOE
NRIC No SXXXX170B

Apply PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

170B

Vehicle Details

Vehicle No.:

SML9008C

Vehicle to be Exported:

No

Intended Deregistration Date:

16 Feb 2022

Vehicle Make:

TOYOTA

Vehicle Model:

FORTUNER 2WD AUTO

Primary Colour:

Grey

Manufacturing Year:

2013

Engine No.:

2TR7651185

Chassis No.:

MHFZX69G807058911

Maximum Power Output:

118.0 kW (158 bhp)

Open Market Value:

\$26,578.00

Original Registration Date:

12 Dec 2013

First Registration Date:

12 Dec 2013

Transfer Count:

2

Actual ARF Paid:

\$29,210.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

11 Dec 2023

PARF Rebate Amount:

\$16,065.00

Intended COE Rebate Details

COE Expiry Date:

11 Dec 2023

COE Category:

B - Car (1601cc & above)

COE Period(Years):

10

QP Paid:

\$76,389.00

COE Rebate Amount:

\$13,891.00


Total Rebate Amount:

\$29,956.00

The information contained herein is correct as at 16 Feb 2022

OK

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/2/22 at 11:15 am. I was driving my vehicle (A) SML9008C at Portsdown Flyover towards Alexandra. When I turn right, suddenly my vehicle hit onto the curve/kerb and traffic light. No damage to Traffic Light. My car is damaged.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No:

