

ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref: Vehicle No. FBK6180S Type of Claim : Make & Model HONDA CB400X Year of Manufacture Chassis No. Ins Company FIRST CAPITAL Engine No. **Excess** Policy No. : D-21097290MFCE/111 Date of Accident 28/05/21 Time of Accident : 14.15 Suggested Days of Repair : In-house Vehicle Assessor Case Owner Repair Estimates Signature Parts (a) Cost / List Price Items \$ 9,865.00 Contact No Plus/Less \$ \$ Total of Cost / List 9,865.00 (b) Nett Price Items \$ -Less Total of Nett Item (c) Special Nett Items Total Parts Cost (Appendix A) 9,865.00 Labour (Appendix B) 1,200.00 **Total Repair Cost** 11,065.00 The above total will be subjected to 7% G.S.T. Name of Supreyor

Name of Surveyor	\$1		
Company	(3)		
Survey conducted on	3	at	
Remarks By Surveyor	outhorized / is and outhorized		
(a) The repair of this vehicle is	authorized / is not authorized	until further notice.	
(b) Recommended Days of Re	pair :	day(s)	
(c) Resurvey	: Required / Not Requir	ed	
(d) Excess	:\$		
(e) Signature of surveyor	1	Date:	

Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649 TEL:68438723/68438736 Fax:67436072

Spare Parts

Vehicle No	FBK6180S	Case Owner : 0
Make & Model	: HONDA CB400X	Year Manufacture : 0
Chassis No	: 0	Engine No : 0
Sales Order	ž	Supplier :
Order By	ž	Type of Claim <u>0</u>

S/No Par	Part Description	QTY	Cost Price	List	N	ett	S/N	Disposition By Surveyor
				Price	Pi	rice		
1	Rear Seat Cowling	1		\$ 450	0.00			
2	Rear Side Box Rack	1		\$ 280	0.00			
3	Rear Body Frame	1		\$ 3,500	0.00			
4	Rear L/H Pillion Footrest Bracket	1		\$ 95	5.00			
5	Rear R/H Pillion Footrest Bracket	1		\$ 95	5.00			
6	Rear Blinker Light	1		\$ 450	0.00			
7	Rear Blinker Pole	1		\$ 390	0.00			
8	Rear Box Rack	1		\$ 285	5.00			
9	Rear Number Plate	1		\$ 35	5.00			
10	Chain Adjuster	1		\$ 45	5.00			
11	Brake Lever	1		\$ 45	5.00			
12	Front Master Pump Cylinder	1		\$ 280	0.00			
13	Siren	1		\$ 950				
14	Right Side Cover	1		\$ 90	0.00			
15	Front Headlight Lower Cover	1			0.00			
16	Fairing Decal	1			0.00			
17	Handle Bar	1			0.00			
18	Handle Barend	2			0.00			
19	Rear Crashbar Set	1			0.00			
20	Brake Pedal	1		\$ 180				
21	Exhaust Protector	1			5.00			
22	Exhaust Muffler	1			0.00			
23	Side Box Set	1		\$ 360				
24	Customize Decals	1		\$ 250				
25				,				
26								
27								
28								
29								
30								

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spark Car Care

ComfortDelGro Engineering Pte Ltd 320 UBI ROAD 3 SINGAPORE 408649

Tel: 68438723/68438736 FAX: 67436072

<u>Labour</u>

Vehicle No. : FBK6180S		Case Owner	1	. 0			
Make & Model : _	HONDA CB400X	Year of Manufacture	* <u></u>	0			

S/No	Labour Description	Esimated Price	Adjusted Price
1	RESPRAY & PUTTY WORKS		Frice
	LABOUR	\$800.00	
	LABOUR	\$400.00	
		-	
		-	
	n n		
		+	
		+ +	
-			

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.