



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBK 6180S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR SEAT COWLING	MISSING	450.00	450.00
1	REAR SIDE BOX RACK	BROKEN	280.00	280.00
1	REAR BODY FRAME	TO REPAIR SEE LABOUR	3,500.00	-
1	REAR L/H PILLION FOOTREST BRACKET	BROKEN	95.00	95.00
1	REAR R/H PILLION FOOTREST BRACKET	BROKEN	95.00	95.00
1	REAR BLINKER LIGHT	BROKEN	450.00	450.00
1	REAR BLINKER POLE	BENT	390.00	390.00
1	REAR BOX RACK	BENT	285.00	285.00
1	REAR NUMBER PLATE	BENT	35.00	35.00
1	CHAIN ADJUSTER	BENT	45.00	45.00
1	BRAKE LEVER	CUT	45.00	45.00
1	FRONT MASTER PUMP CYLINDER	NOT NECESSARY	280.00	-
1	SIREN	BROKEN	950.00	950.00
1	RIGHT SIDE COVER	BROKEN	90.00	90.00
1	FRONT HEADLIGHT LOWER COVER	CUT	120.00	120.00
1	FAIRING DECAL	NECESSARY	300.00	300.00
1	HANDLE BAR	BENT	180.00	180.00
2	HANDLE BAREND	BENT	50.00	50.00
1	SET REAR CRASHBAR	BENT	580.00	580.00
1	BRAKE PEDAL	BENT	180.00	180.00
1	EXHAUST PROTECTOR	CUT	75.00	75.00
1	EXHAUST MUFFLER	BENT	780.00	780.00
1	SET SIDE BOX	BROKEN	360.00	360.00
1	CUSTOMIZE DECALS	NECESSARY	250.00	250.00
	LESS 10% DISCOUNT		-	-608.50
			9,865.00	5,476.50
	<u>LABOUR</u>			
	RESPRAY & PUTTY WORKS.		800.00	500.00

Report Ref No. CS/FCI22001581/Evy3m4



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR. INCLUSIVE OF THE REPAIR OF REAR BODY FRAME.		400.00	300.00
			1,200.00	800.00
	GRAND TOTAL		11,065.00	6,276.50

RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)			6,276.50
LESS EXCESS			-1,500.00
NETT LIABILITY			4,776.50

Report Ref No. CS/FCI22001581/Evy3m4

MARKET VALUE: \$8,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$2,286.00=NETT VALUE: \$5,714.00

CHEN TSUE YEE

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.