3/9/22, 3:12 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001582/AVY3N2

09/03/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No: DMPCSNW00095362101

Claimant Vehicle

SMZ7650L

Insured Vehicle No:

SKW7431S

No:

Nature of

Date of Loss:

16/02/2022

TP Claim:

Claim

Odometer:

SNM22D201221/C02/TANCHC

62347 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMZ7650L Reg No:

G4FMMU015743 Make & Model: HYUNDAI CN7 AVANTE 1.6, 1.6 (A) Engine No: Reg. Date: 18/05/2021 (Man. Year: 2021) Chassis No: KMHLN41ETNU184773

Colour: Grey

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16 Front Left Side: Rear Left Side: Hankook 6 mm Hankook 6 mm Front Right Side: Rear Right Side: Hankook 6 mm Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,378.80	2,568.08	2,810.72	52.26
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,750.00	530.00	1,220.00	69.71
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,128.80	3,098.08	4,030.72	56.54
	Approved Total (Overridden) (S\$)		2,450.00		
	Nett Amount (S\$)	7.128.80	2.450.00	4.678.80	65.63

INSPECTION

Date Inspected:

Date of Assignment: 18/02/2022

AUTOMOBILE HUB ENTERPRISE

1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY

SINGAPORE 417883

Estimated Period of Repair: 3.0 days

Adjuster: **ADRIAN LING** Manager: **VERON CHEN**

18/02/2022

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Inspected At:

3/9/22, 3:12 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Mar 2022)

Parts: 143 HYUNDAI CN7 AVANTE 1.6 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMZ7650L)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	499.70 F	*- FL
2	1		*FRONT BUMPER SIDE HOLDER RH	Not Necessary	35.90 F	*- FL
3	1		*HEADLAMP RH	Cracked	1,756.40 F	*1,756.40 FL
4	1		*FRONT RH FENDER	Distorted	1,227.70 F	*1,227.70 FL
5	1		*FRONT RH FENDER INNER SHIELD	Deformed	188.50 F	*188.50 FL
6	1		*FRONT RH LOWER ARM	Not Necessary	465.20 F	*- FL
7	1		*FRONT RH WHEEL HUB C/W BEARING	Not Necessary	295.40 F	*- FL
8	1		*FRONT BUMPER CLIPS	Not Necessary	30.00 FS	*-FS
9	1		*FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS
10	1		*FRONT RH WHEEL RIM	Not Necessary	850.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett. L=ListItemDisc.	Sub Total (S\$)	5,378.80	3,202.60
			- List Item Discount on I	L Items 0.00/20.00% (S\$)	0.00	634.52
				Total Parts (S\$)	5,378.80	2,568.08
			Report was unsubmitted durin	g this print-out.		

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING	New	700.00	300.00
2	SPRAY PAINTING	New	600.00	200.00
3	WIRING	New	50.00	30.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
5	TO DISMANTLE FRONT UNDERCARRIAGE	New	250.00	0.00
		Gross Labour Cost (S\$)	1,750.00	530.00
	Report was un	submitted during this print-out.		

< END OF ESTIMATES >