

TP China.
Veron.

SMZ 7650L 2021 May
Hyundai Avante 1598cc
KMHLN41ETNU184773

Front Bumper	2 M m	499.70 +
Front Bumper Clips.		30(SN) +
Front Bumper Side Holder RH.		35.90. +
Headlamp RH.	Cracked	1756.40. ✓
Front RH Fender	Distorted	1227.70 ✓
Front RH Fender Inner Shield	Distorted	188.50. ✓
Front RH Fender Inner Shield clips	M	30(SN) ✓
Front RH Wheel Rim.	M	850(SN) +
Front RH Lower Arm.	M	465.20 +
Front RH Wheel Hub c/w Bearings.	M	295.40. +

3172.60 S.N. 30
2538.08

SMZ 7650L.

Panel Beating

530

~~700~~ 300

Spray Painting.

~~600~~ 200

Wiring

~~50~~ 30

To perform wheel alignment

150 X

To dismantle front undercarriage.

250 X

7068.80

total: 3098.08

n/s: 2450.

03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey; is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: