



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717 ON BEHALF OF YEO BUAY KIANG & PATRICIA YEO			Ref: CS/TP22001583/Aqy3n2 Date: 24/02/2022 Code: TP202	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SLC 9761U	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	11/02/2022	
2. Vehicle Particulars & Condition				
	Make & Model	HYUNDAI ELANTRA	c.c	1591
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	KMHD841CMHU195164	Colour	BLUE
	Odometer	102090 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195/65 R15	NEXEN	6 mm
	L/H Front Tyre	195/65 R15	NEXEN	6 mm
	R/H Rear Tyre	195/65 R15	NEXEN	6 mm
	L/H Rear Tyre	195/65 R15	NEXEN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/01/2022	Inspection Date	11/02/2022
	Survey held at	PEOPLE'S VEHICLE RECOVERY SERVICE BLK 3023-A, UBI ROAD 1 #01-60 SINGAPORE 408717		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	