

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001584/AVY3N2**Date:** 10/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00220702100

**Claimant Vehicle No :** SLV5729R **Insured Vehicle No :** SJG6776A

Date of Loss: 12/02/2022 Nature of Claim: TP Claim No: SNM22D201088/C02/TANKW

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No: **SLV5729R**

Make & Model: HONDA HR-V, 1.5 LX CVT (A) Engine No: L15B4533550

Reg. Date: 03/01/2018 (Man. Year: 2017) Chassis No: JHMRU1830GX203550

Colour: Bronze Odometer: 32361 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16

Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,998.70	2,103.04	1,895.66	47.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	830.00	570.00	40.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,398.70</b>	<b>2,933.04</b>	<b>2,465.66</b>	<b>45.67</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,350.00</b>		
<b>Nett Amount (S\$)</b>	<b>5,398.70</b>	<b>2,350.00</b>	<b>3,048.70</b>	<b>56.47</b>

**INSPECTION**

Date of Assignment: 18/02/2022

Date Inspected: 21/02/2022 Inspected At: Automobile Hub Enterprise  
1 KAKI BUKIT AVENUE 5, #2 -11 AUTOBAY @ KAKI BUKIT  
Singapore 417883

Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 08 Mar 2022)	
Parts:	N/A	HONDA HR-V 1.5 LX CVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLV5729R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	495.80 F	*495.80 FL
2	1		*FRONT BUMPER SIDE HOLDER RH	Damaged	35.10 F	*35.10 FL
3	1		*HEADLAMP RH	Cracked	1,820.90 F	*1,820.90 FL
4	1		*HEADLAMP LOWER BRACKET RH	Cracked	48.00 F	*48.00 FL
5	1		*FRONT RH FENDER	Repair	582.40 F	*- FL
6	1		*FRONT RH FENDER WHEEL ARC GARNISH	Cut	166.50 F	*166.50 FL
7	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
8	1		*FRONT RH FENDER WHEEL ARC GARNISH CLIPS	Necessary	20.00 FS	*20.00 FS
9	1		*FRONT RH WHEEL RIM	Not Necessary	800.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (S\$)					3,998.70	2,616.30
- List Item Discount on L Items 0.00/20.00% (S\$)					0.00	513.26
Total Parts (S\$)					3,998.70	2,103.04

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING	New	600.00	300.00
2	SPRAY PAINTING	New	600.00	500.00
3	WIRING	New	50.00	30.00
4	TO PERFORM WHEEL ALIGNMENT	New	150.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,400.00</b>	<b>830.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >