

Att: Kenneth

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL 67556142 (YIS) FAX 67557719 (YIS) Email: chmotor@singnet.com.sg
GST 201001158E RCB NO 201001158E

M/S: MS FIRST CAPITAL INSURANCE LTD

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

WS Ref: TP/MSFC/AMK

Claim Type: Third Party

Accident Date: 17/02/2022

TP Veh Reg No: GBJ7839A

Estimate No: ES2290173/AMK

Date: 24 Feb 2022

Policy No: DMPCSNW00121192100

Veh Reg No: SMU2043Z

Make/Model: BMW 218i

Chassis No: WBA2M120X07D62831

Engine No: 31715627B38B15A

Reg. Date: 29/11/2019

Estimate Repair Cost to Vehicle No :SMU2043Z

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	906.00	1 PC	906.00	—
2 FRONT BUMPER CENTRE LOWER GRILLE	126.00	1 PC	126.00	XX NN
3 FRONT BUMPER RH FOG LAMP	461.00	1 PC	461.00	XX NN
4 FRONT BUMPER RH FOG LAMP COVER	107.00	1 PC	107.00	—
5 FRONT BUMPER RH FOG LAMP COVER TRIM	76.00	1 PC	76.00	—
6 FRT BUMPER LOGO	96.00	1 PC	96.00	—
7 FRONT BUMPER RH AIR DUCT	55.00	1 PC	55.00	XX NN
8 HEADLAMP RH	2,596.00	1 PC	2,596.00	—
			3781	4,423.00
		Less 10%	442.30	3,980.70
			378.10	3402.90
Special Net				
9 BODY WRAPPING STICKER	600.00	1 PC	600.00	?/
			600.00	600.00
Labour				
10 REMOVE & REFIX FRT BUMPER,GRILLE, & ATTACHMENTS,RH HEADLAMP;KNOCKING & REPAIR FRT RH FENDER & REALIGN THE SAME	450.00	1 LA	450.00	300L
11 PUTTY & RESPRAY FRT BUMPER & ALL AFFECTED AREAS	300.00	1 LA	300.00	250L
			750.00	750.00 550
			Total	S\$ 5,330.70
			Add GST @ 7%	373.15
			Total Amount Payable	S\$ 5,703.85

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn L

AUTHORISED SIGNATURE

PARTS: 3402.90

SA: 550

L: 550

4502.90

P/P: 4502.90/2

PLS CHECK & CONFIRM