

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Repair Estimate

Vehicle number: SGH3S

Make & Model: Porsche Macan PDK CYP

Chassis number: WP1ZZZ95ZHLB05510

2016

No.	Description of spare parts	Qty	Amount
1	Front bumper 1084.90	1	\$ 1,623.00
2	Front bumper LH side bracket ✓	1	\$ ✓ 244.00
3	Front LH fender "upper" ✓	1	\$ ✓ 1,121.00
4	Front LH fender "lower"	1	\$ -642.00
5	Front LH fender splash shield	1	\$ 231.00
6	Front LH sport rim ✓	1	\$ ✓ 2,462.00
7	Front LH shock absorber 895.00	1	\$ 1,632.00
8	Front LH lower arm 899.50	1	\$ 1,342.00
9	Front LH lower arm ball joint ✓	1	\$ ✓ 113.00
10	Front LH knuckle arm 1425.20	1	\$ 1,732.00
11	Front LH wheel bearing 420.00	1	\$ 441.00
12	Front LH upper arm 799.50	1	\$ 1,022.00
13	Front LH control arm 700.00	1	\$ 903.00
14	Front LH door 2027.20	1	\$ -3,321.00
15	Front LH door lower protector 217.00	1	\$ 299.00
16	Front LH weatherstrip ✓	1	\$ ✓ 393.00
17	Front LH door frame trim tape	1	\$ 178.00
18	LH side mirror assy	1	\$ 1,436.00
19	LH side rocker panel garnish 320.00	1	\$ 454.00
20	LH side rocker panel garnish sponge	2	\$ 121.00
21	Rear LH door 1989.40	1	\$ 3,482.00
22	Rear LH door lower protector 217.00	1	\$ 299.00
23	Rear LH door inner insulator	1	\$ -16.00
24	Rear LH door weatherstrip seal ✓	1	\$ ✓ 393.00
25	Rear LH door stone guard sticker ✓	1	\$ ✓ 147.00
26	Rear LH door frame trim tape	1	\$ 178.00
27	Rear LH sport rim	1	\$ 2,462.00
28	Rear LH lower arm	1	\$ 1,152.00
29	Rear LH shock absorber	1	\$ 1,347.00
30	Rear LH knuckle arm	1	\$ 1,608.00
31	Rear LH track control arm	1	\$ 932.00
32	Rear LH upper arm	1	\$ 731.00

CUT ✓
 NEC ✓
 DD ✓
 NSX
 NDX
 CUT ✓
 DD ✓
 BT ✓
 DD ✓
 2DD ✓
 JMV ✓
 BT ✓
 BT ✓
 DD ✓
 CUT ✓
 NEC ✓
 NSX
 NDX
 DD ✓
 NSX
 DD ✓
 CUT ✓
 NSX
 NEC ✓
 NEC ✓
 NNX
 NDX

33	Rear LH fender	1	\$	5,531.00
34	Rear LH fender glass with rubber seal	1	\$	405.00
35	Rear LH fender protective flim	1	\$	113.00
36	Rear LH fender clinch pins	6	\$	86.00
37	Rear LH fender splash shield	1	\$	443.00
38	Rear bumper	1	\$	1,633.80
39	Rear bumper lower garnish	1	\$	645.00
40	Rear bumper LH side bracket	1	\$	244.00
		Total	\$	41,557.80
		Less 10%	\$	4,155.78
		Total	\$	37,402.02

NDX
NDX

No.	Special Nett Items	Qty	Amount
1	Front LH fender spalsh shield clips (set)	1	\$ 75.00
2	Front LH tyre	1	\$ 580.00
3	Rear LH tyre	1	\$ 580.00
4	Brake fluid	2	\$ 120.00
5	Front LH door inner trim board clips (set)	1	\$ 30.00 70.00
6	Rear LH door inner trim board clips (set)	1	\$ 70.00
7	Rear bumper clips (set)	1	\$ 80.00
8	Front bumper clips (set)	1	\$ 30.00 80.00
			60.00

NNX
NECV
NNX
NNX
NECV

Total: \$ 1,655.00

	Labour and painting	Amount
1	Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut/weld and realign all affected panels and areas	\$ 1200.00 2,000.00
2	Spray painting on affected areas and panels	\$ 1000.00 1,600.00
3	Check wiring and lighting system	\$ 100.00
4	Apply rust coating chemical on affected areas and panels	\$ 150.00
5	Test drive and adjust wheel alignment system	\$ 60.00 150.00
6	Remove and replace front undercarriage parts to assist repair	\$ 300.00 550.00
7	Remove and replace front LH door inner mechansim to new door	\$ 80.00 180.00

NNX

8	Remove and replace rear LH door inner mechanism to new door		\$	180.00	RPT X
9	Remove and replace rear inner trims, carpet, roof lining, seats and boards to assist repair		\$	550.00	NNX
10	Remove and replace rear undercarriage parts to assist repair		\$	550.00	NNX
11	Remove and reinstall rear bumper reverse sensors to assist repair		\$	180.00	NNX
12	Reset and diagnose control unit and fault codes		\$	120.00 350.00	✓
				2760.00	

Total: \$ 6,540.00

Survey
21/2/2022
1475
Train

Resurvey
25/2/2022
1400hrs
Train

Spare Parts: \$ 37,402.02
Special Nett: \$ 1,655.00
Labour: \$ 6,540.00

Total Amount: \$ 45,597.02

Parts 17,459.55
SN 60.00
Labour 2,760.00
20,279.55
@ 2070 4,055.91
16223.64

LS 15K

Train
17/3/2022

K&A Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Parts price revised and Supplementary

Vehicle number: SGH3S

Make & Model: Porsche Macan PDK CYP

No.	Description of spare parts	Qty	Amount
1	Headlamp garnish LH	1	\$ 286.00
2	Bonnet	1	\$ 2,455.00
3	LH front door inner trim board	1	\$ 1,321.00
		Total	\$ 4,062.00
		Less 10%	\$ 406.20
		Total	\$ 3,655.80

2016

BAV
DDV Rm
BRV S12**Total Amount****\$****3,655.80**

Resurvey

25/2/2022

Total in

14 Hrs

Lump sum repair

Repair days 12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Supplementary estimate

Vehicle number: SGH3S

Make & Model: Porsche Macan PDK CYP

No.	Description of spare parts	Qty	Amount
1	LH headlamp assy	1	\$ 3245.80 6,304.00
		Total	\$ 6,304.00
		Less 10%	\$ 630.40
		Total	\$ 5,673.60

Total Amount**\$****5,673.60**

Resurvey

25/2/22

1400hrs

T. Lim