

EURO SUCCESS SERV PTE. LTD
1 KAKIT BUKIT AVE 6, #02-03 SINGAPORE 417883

TEL: 67426231

FAX: 67411019

Vehicle No: SMD2682T

Model: HYUNDAI ELANTRA

not Arrived
1/5 3800 4 hrs.
18/2/22
H/P: 98289277 (Ah Huat)

NI / NA
NI / NA

QTY	LIST ITEMS	AMOUNT
1	REAR BUMPER D.S	498 \$580.00
1	REAR BUMPER LOWER PAD KIT De	241 \$290.00
2	REAR BUMPER REFLECTOR L-R @85 MS one	68.00 \$170.00 1PC
2	REAR BUMPER BRACKET L-R @76 MS Two	48.00 \$152.00 1PC
1 set	REAR BUMPER CLIP @6.50	45 \$65.00
1	REAR BUMPER reinforcement D.S	341 \$350.90
1	REAR END PANEL	\$428.00
1	REAR END PANEL INNER BOARD Two	184.20 \$310.00
1	REAR BOOTLID	\$950.10
1	REAR BOOTLID GARNISH	\$185.60 X
2	REAR BOOT INNER LOCK TOP & BOTTOM LOCK	\$255.70 X
1	REAR BOOT LAMP L-R @870	\$1,740.00 X
1	REAR BOOT EMBLEM	\$50.00 X
1	REAR BOOT LOGO	\$65.00
2	REAR BOOT 'ELANTRA' EMBLEM	\$65.00
2	REAR BOOT 'S' EMBLEM	\$45.00
1	REAR BOOT WEATHER STRP	\$155.00 X
1	REAR TAIL LAMP L-R @620.00	\$1,240.00 1PC
1	REAR TAIL LAMP BRACKET L-R @125.00	\$250.00 X
2	REAR FENDER L-R @950	\$1,900.00 X
2	REAR FENDER INNER TRIM BOARD L-R @310	\$620.00 X
1	REAR SPARE TYRE BOARD	\$230.00 X
1	REAR EXHUAUST BOX	\$580.50 X
TOTAL		\$10,677.80
LESS 20%		\$2,135.56
TOTAL		\$8,542.24

SPECIAL NETT ITEMS		
1	REAR BUMPER PLATE NS	\$55.00 X
1	REAR NUMBER PLATE BOX	\$120.00 X
1 set	REAR BUMPER REVERSE SENSOR	\$350.00 200
1 set	REAR BUMPER CLIPS	\$55.00 X
1	REAR BOOT LID INNER trim CLIPS	\$50.00 50
1	REAR FENDER CLIPS	\$50.00 X
1	REAR TAIL LAMP CLIPS	\$30.00 X
TOTAL		\$710.00

LABOUR CHARGES

TO REMOVE AND REFIX REVERSE SENSOR	\$100.00 50
TO REMOVE AND REFIX EXHAUST BOX	\$80.00 X
TO REMOVE, REFIT, REPLACE LAMP AND CHECK WIRING	\$80.00 20

Yr Rean: 13/8/18

11/07/13

12/

TO APPLY UNDERCOATING ON ACCIDENT PARTS
TO KNOCK REAR END PANEL, BOOT LID, FENDER AND REMOVE
AND REPLACE RE-ALIGNMENT ON DAMAGED PARTS
TO TRANSFER REAR BOOT LID AND WIRING
TO PUTTY & SPRAY PAINTING

\$450.00 60
\$1,500.00 600
\$200.00 60
\$1,200.00 900
\$3,610.00

TOTAL

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$12,862.24

commenc
ime of in:
days
%
4 HRS
n Conta
struction
27
38

mm
mm

lision

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-35768
202
P-2861.52
S.N. 250
1690