


PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408899

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORTH@AIGPREMIUM.COM SINGAPORE@AIGPREMIUM.COM

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0119/2022/JT
DATE : 17-Feb-22
WIP : 12258

Xiao Tony

\$ 3346.80

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 22/2/22

YOUR INSURED VEH NO : GBE 2555 C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TEO CHUAN MING
ADDRESS : 6 BISHAN ST 25
#12-10
SINGAPORE 573975
TELEPHONE : HP +65 97633258
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5100867315-03
VEHICLE NO : SLP 7146 R
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI
MODEL YEAR : 15/6/2017
ENGINE NO : CVN 038477
CHASSIS NO : WAUZZZF45HA161698
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Feb-22
PLACE OF ACCIDENT : AYE (MCE) BEFORE ALEXANDRA ROAD
EXIT, LANE 1

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408695
TEL: 6356 2123 FAX: 6341 1183

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 7146 R

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00	✓ ✓
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$ 1,050.00	500 ✓
3	TO RESPRAY REAR BUMPER.	\$ 900.00	550 ✓
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 2,502.00	

PREMIUM AUTOMOBILES

DE UB ROAD 1 SINGAPORE 10509
TEL: 63662223 FAX: 63661152
E-MAIL: NIPAN@PREMIUMAUTOMOBILES.COM.SG CLAIMS@PREMIUMAUTOMOBILES.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 7146 R

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Deformed</i>	1	\$ 2,181.00	✓	1,744.80
2	REAR BUMPER FIXING PARTS <i>Not in</i>	1	\$ 76.00	X	
3	REAR BUMPER SECURING STRIP <i>Not in</i>	1	\$ 249.00	X	
4	REAR BUMPER SPOILER <i>Not in</i>	1	\$ 276.00	X	
5	REAR LIGHT REFLECTOR - LH / RH <i>Not in</i>	2	\$ 92.00	X	
6	REAR BUMPER REINFORCEMENT BEAM <i>Not in</i>	1	\$ 1,131.00	X	
7	REAR BUMPER SEAL <i>Not in</i>	2	\$ 32.00	X	
8	REAR BUMPER GUIDE SECTION UPPER - LH / RH <i>Not in</i>	2	\$ 100.00	X	
9	REAR BUMPER GUIDE SECTION - LH / RH <i>Not in</i>	2	\$ 52.00	X	
10	REAR GUIDE SECTION PIN <i>Not in</i>	2	\$ 6.00	X	
11	REAR PARKING AID SENSOR - INNER / OUTER <i>Not in</i>	2	\$ 488.00	X	
12	REAR PARKING AID SENSOR SEAL RING <i>Not in</i>	4	\$ 10.00	X	
13	SUNDRIES <i>Not in</i>		\$ 250.00	X	
TOTAL SPARE PARTS			\$ 4,943.00		
TOTAL LABOUR CHARGES			\$ 2,502.00		
GRAND TOTAL			\$ 7,445.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES

85 UBI ROAD, SINGAPORE 408691
TEL: 6768 2325 FAX: 6768 1183
EMAIL: MIRA.KHAI@PREMIUM-AUTOMOBILES.COM

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Adrian L
: 22/02/22

: Not Authorised, 03 Days
: [Signature]

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT