

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0119/2022/JT
DATE : 17-Feb-22
WIP : 12258

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 22/2/22

YOUR INSURED VEH NO : GBE 2555 C

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS TEO CHUAN MING
ADDRESS : 6 BISHAN ST 25
#12-10
SINGAPORE 573975
TELEPHONE : HP +65 97633258
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5100867315-03
VEHICLE NO : **SLP 7146 R**
MODEL CODE : AUDI A4 SEDAN 1.4 TFSI
MODEL YEAR : 15/6/2017
ENGINE NO : CVN 038477
CHASSIS NO : WAUZZZF45HA161698
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Feb-22
PLACE OF ACCIDENT : AYE (MCE) BEFORE ALEXANDRA ROAD
EXIT, LANE 1

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLP 7146 R

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S/N \$	1,050.00	
3	TO RESPRAY REAR BUMPER.	\$	900.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	
TOTAL LABOUR CHARGES		: \$	2,502.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLP 7146 R

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,181.00	
2	REAR BUMPER FIXING PARTS	1	\$ 76.00	
3	REAR BUMPER SECURING STRIP	1	\$ 249.00	
4	REAR BUMPER SPOILER	1	\$ 276.00	
5	REAR LIGHT REFLECTOR - LH / RH	2	\$ 92.00	
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,131.00	
7	REAR BUMPER SEAL	2	\$ 32.00	
8	REAR BUMPER GUIDE SECTION UPPER - LH / RH	2	\$ 100.00	
9	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 52.00	
10	REAR GUIDE SECTION PIN	2	\$ 6.00	
11	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 488.00	
12	REAR PARKING AID SENSOR SEAL RING	4	\$ 10.00	
13	SUNDRIES		\$ 250.00	
TOTAL SPARE PARTS		:	\$ 4,943.00	
TOTAL LABOUR CHARGES		:	\$ 2,502.00	
GRAND TOTAL		:	\$ 7,445.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT