



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN: ONG KIAN THENG DERICK			Ref: CS/ASM22001599/Tvy3e2 Date: 15/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLM 2257C	Veh. Inspected	SMP 8888P
	Policy No.	GA568296	Coverage (\$)	0.00
	Claim No.	S2M03TG9	Excess (\$)	0.00
	Assign From	ONG KIAN THENG DERICK	Assign Date	18/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA VELLFIRE	c.c	2493
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	AGH300237566	Colour	WHITE
	Odometer	85019 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50 R18	TOYO	6 mm
	L/H Front Tyre	235/50 R18	TOYO	6 mm
	R/H Rear Tyre	235/50 R18	TOYO	6 mm
	L/H Rear Tyre	235/50 R18	TOYO	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	12/02/2022	Inspection Date	23/02/2022
	Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-59 AUTOBAY @ KKAI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	