

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	📄 ▼	🖨	Find Next
---	---	----------	---	---	---	---	--------	-----	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO22001601/Utf3		
50 RAFFLES PLACE #03-03		Date: 18/02/2022		
SINGAPORE LAND TOWERSINGAPORE 048623		Code: SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	GBL 4280U	Veh. Inspected	GBD 6194P	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2200282/AGC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	18/02/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	19/01/2022	Inspection Date	21/02/2022	
Survey held at	A S AUTO SERVICE NO 1 KAKI BUKIT #01-106 SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				