

Our Job Ref No : 305503881  
Date : 11/02/22

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK  
Attn : THEVAN  
Vehicle Reg No. : SHC8233G


Fax :


Date of Accident : 04/02/22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

- The repair job shall bill to: NTUC --- SMP7163D
- The finalized amount shall be:
  - Spare Parts after List discount \$581.83 X581.85
  - Labour Charges (include advertisement stickers etc,if any) \$1,200.00
  - Total for Part-By-Part Repair Cost \$1,781.83
  - Lumpsum Repair (if applicable) 1781.85
  - Total for Lumpsum repair cost after Less: 20%
  - Final Lumpsum Repair cost
- Estimated normal period for repairs: 3 working days.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
- Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : THEVAN  
Date :

#### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_  
\_\_\_\_\_

COMFORTDELORO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 10.02.2022  
Time: 16:19:27  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

KOR NO : 303303481  
REGN NO : SHC8213G  
MILEAGE : 0000000000  
MAKE : TOYOTA  
MODEL : PRIUS HYBRID(G4A)  
DATE OF REGN : 19.02.2020  
DATE/TIME IN : 04.02.2022 13:40  
ACCIDENT DATE : 04.02.2022

JOB / PARTS DESCRIPTION

QTY IND UNIT PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0302-2534-G	FRT BUMPER	1	499.90	25.00	374.92
0002	04-01-0302-2267-G	FRT BUMPER CLIPS	10	22.00	25.00	16.50
0003	04-01-0302-2685-G	FRT BUMPER GRILLE LH	1	*85.10	25.00	63.82
0004	04-01-0302-2871-G	FRT BUMPER SIDE BRKT LH	1	82.30	25.00	61.72
0005	04-01-0302-2297-G	EMBLEM SIDE PANEL (HYBRID U)	1	86.50	25.00	64.87

SUB-TOTAL : 581.83

JOB NATURE

000 PB	PANEL BEATING-SHC8233G	700.00
0001 SP	SPRAYPAINT CHARGE	500.00

SUB-TOTAL : 1,200.00

TOTAL : 1,781.83

*Lmfs*  
MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

\* Corrected price

Effective Date: 1 Nov 2020

LKK -

INSURANCE: NTUC CP P

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Bumper Cover	1		\$499.90 ✓
	Front Bumper Clips	10	\$2.20	\$22.00 ✓
	Front Bumper Grille LH	1		\$28.30 ✓
	Front Bumper Side Retainer LH	1		\$77.00 ✗
	Front Bumper Side Bracket LH	1		\$82.30 ✓
	Front Fender LH	1		\$945.30 ✓
	Front Fender Hybrid LH	1		\$86.50 ✓
	SUB TOTAL			\$1,741.30
	LESS 25%			\$435.33
	DISCOUNTED TOTAL			\$1,305.98
	<u>Labour Charge</u>			
	Panel Beating			\$800.00
	Spray Painting Charge			\$600.00
	TOTAL LABOUR			\$1,400.00
	ESTIMATE TOTAL			\$2,705.98

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran @~~21~~ 82235769  
7/2/22 1700  
P/P bfr para photo  
3clays wp

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

**Signature:**

Date: