

Our Job Ref No : 305503883

Date : 12/02/22

COMFORTDELGRO
ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : Thevaan

Vehicle Reg No. : SHC1197Z

03/02/22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

Z The repair job shall bill to: MTC SHD5163P

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

Final Lumpsum Repair cost

\$1,550.00

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as **Correct and Confirmed** if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : CHIANG

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature :

Name :

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1197Z

04/02/22

MAKE REG 06.09.2018

CHIANG/NTUC

MODEL IONIQ G

Qty	Parts Description/ Labour	Type
1	REAR BUMPER	
1	REAR BUMPER SIDE BRACKET RH	
1	REAR BUMPER REINFORCEMENT	
1	REAR BUMPER CENTRE MOULDING	
1	REAR BUMPER REFLECTOR RH	
2	NUMBER PLATE LAMP LH/RH	
1	REAR FOG LAMP	
10	REAR BUMPER CLIPS	
SUB TOTAL		
20.00%		
DISCOUNTED TOTAL		
2	REAR FENDER ADVERTISEMENT LH/RH	
1	REAR BUMPER MAT	
1	REAR NUMBER PLATE W/HOLDER	
1	REAR REVERSE SENSOR	
Labour Charge		
Panel Beating		
Spray Painting Charge		
Check Lighting and Wiring		
Tuff Kote		
Remove/refix Reverse sensor		
TOTAL LABOUR		
ESTIMATE TOTAL		

Amount
\$459.40
\$55.80
\$394.80
\$451.25
\$41.45
\$85.30
\$201.50
\$22.00
\$1,711.50
\$342.30
\$1,369.20
\$200.00
\$50.00
\$55.00
\$180.00
\$461.50
\$500.00
\$300.00
\$60.00
\$60.00
\$60.00
\$980.00
\$2,810.70

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan 82255769
7/2/22 1 645
48 better repair photo
2 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: