



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001613/Etf3e2	
			Date: 25/05/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YN 9826E	Veh. Inspected	SMP 3812R
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000489MFCV	Excess (\$)	0.00
	Assign From	JOANNE TAN JO ANN	Assign Date	18/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA 3	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	JM6BP2SAAK1100926	Colour	GREY
	Odometer	40310 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	DUNLOP	4 mm
	L/H Front Tyre	205/60 R16	DUNLOP	4 mm
	R/H Rear Tyre	205/60 R16	DUNLOP	4 mm
	L/H Rear Tyre	205/60 R16	DUNLOP	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	16/02/2022	Inspection Date	23/02/2022
	Survey held at	27A Tanjong Penjuru		
	Repairer	TRANS EUOKARS PTE LTD		
5a. Remarks				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	