

J.E.W MOTORS PTE LTD

Address: 60 Jalan Lam Huat, #03-72

CARROS CENTER, Singapore 737869

Repair Estimate

Vehicle number: SJS105M

Alfa Romeo 1300

No.	Spare parts	Qty	Amount
1	Bonnet <i>lt/</i>	1	\$ 3,850.00
2	Bonnet RH hinge <i>lt/</i>	1	\$ 210.00
3	Bonnet LH hinge <i>lt/</i>	1	\$ 210.00
4	Bonnet lock <i>X</i>	1	\$ 676.00
5	Bonnet rubber seal <i>lt/</i>	1	\$ 289.00
6	Front RH signal lamp <i>X</i>	1	\$ 576.00
7	Front LH signal lamp <i>X</i>	1	\$ 576.00
8	RH headlamp <i>X</i>	1	\$ 2,117.00
9	RH headlamp chrome ring <i>X</i>	1	\$ 312.00
10	LH headlamp <i>X</i>	1	\$ 2,117.00
11	LH headlamp chrome ring <i>X</i>	1	\$ 312.00
12	Front grille <i>X</i>	1	\$ 499.00
13	Front grille chrome <i>X</i>	1	\$ 431.00
14	Front grille emblem <i>X</i>	1	\$ 207.00
15	Front grille RH chrome moulding <i>X</i>	1	\$ 619.00
16	Front grille RH chrome moulding mesh <i>X</i>	1	\$ 378.00
17	Front grille LH chrome moulding <i>X</i>	1	\$ 619.00
18	Front grille LH chrome moulding mesh <i>X</i>	1	\$ 378.00
19	Front bumper <i>X</i>	1	\$ 2,331.00
20	Front bumper number plate holder <i>X</i>	1	\$ 122.00
21	Front bumper RH bracket <i>X</i>	1	\$ 341.00
22	Front bumper LH bracket <i>X</i>	1	\$ 341.00
23	Support panel <i>repair</i>	1	\$ 2,909.00
24	Body panel <i>bu</i>	1	\$ 9,877.00
25	Front air condenser <i>X</i>	1	\$ 1,078.00
26	Front high pressure hose <i>X</i>	1	\$ 119.00
27	Front low pressure hose <i>X</i>	1	\$ 119.00
28	Front wiper panel <i>repair</i>	1	\$ 899.00
			\$ 32,512.00
Less 10%			\$ 3,251.20
Total			\$ 29,260.80

No.	Spare parts	Qty	Special Nett
1	Front number plate X	1	\$ 80.00
2	Radiator coolant X	1	\$ 120.00
3	body panel sealant ?	1	\$ 600.00 ?

LABOUR

1	Labour charges to provide workmanship cut / weld and replacing of parts	\$	2,300.00 500
2	Spray paint on affected and consistent areas	\$	1,200.00 500
3	Check wiring and lighting system	\$	120.00 X
4	Apply rust coating on affected areas	\$	80.00 60
5	Remove and refit aircon condenser and refill aircon gas	\$	220.00 X
6	Remove and refit radiator assy and refill coolant - photo?	\$	220.00 220.00 60

Total Amount: \$ 34,200.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

4 days

4s

22/02/22 @ 1520

Resy after repair