

Policy No : SP2000440008
Date of Accident : 16 February 2022

Claims Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 21 February 2022

Estimate To Repair SMD585D - Toyota PRIUS PLUS (AUTO)
Chassis No : JTDZS3EU70J030203

S/No	Quantity	Description	Amount
		<u>Cost</u>	
01	1 pc N/S	o/n front fender ✓ BT	\$ 210 195.00 ✓✓
02	1 pc //	o/n inner fender cowling X NN	\$ 85.00
03	1 pc //	o/n front fender hybrid emblem ✓ NEC	\$ 25.00 ✓
04	1 pc //	o/n front fender wind deflector X NN	\$ 35.00
05	1 pc //	o/n front door ✓ BUC	\$ 450.00 ✓✓
06	1 pc //	o/n front door outer handle ✓ CUT	\$ 140.00 ✓✓
07	1 pc //	o/n front door outer handle extension ✓ CUT	\$ 18 30.00 ✓✓
08	1 pc //	o/n front door outer moulding X NN	\$ 40.00
09	1 pc //	o/n front door lock X NN	\$ 240.00
10	1 pc //	o/n front door power window motor X NN	\$ 245.00
11	1 pc //	o/n front door power window regulator X NN	\$ 75.00
12	1 pc //	o/n front door weather strip X NN	\$ 60.00
13	1 pc //	o/n side mirror cover X Repair	\$ 38.00
14	1 pc //	o/n side mirror signal lamp ✓ CRA	\$ 25.00 ✓✓
15	1 pc //	o/n rear door ✓ BUC	\$ 420.00 ✓✓
16	1 pc //	o/n rear door outer moulding X NN	\$ 40.00
17	1 pc //	o/n rear door weather strip X NN	\$ 60.00
18	1 pc //	o/n rear fender X Repair	\$ 380.00
19	1 pc //	o/n rear fender stickert X NN	\$ 25.00
20	1 pc //	o/n rear wheel cap ✓ CUT	\$ 85.00 ✓✓
		Add 10 %	\$ 2,693.00
			\$ 269.30
			\$ 2,962.30
		<u>Cost</u>	
21	1 pc	o/n fender quater glass prime X NN	\$ 80.00
22	1 pc	o/n fender quater glass sealant X NN	\$ 80.00
		Add 10 %	\$ 160.00
			\$ 16.00
			\$ 176.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Putty and spray painting on left side of the affected portion.	\$ 1,200.00 800
02		Panel beating, knocking and straighten on left side of the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 850.00 500
03		To rust-proofing of the affected areas.	\$ 120.00 X NN
04		To transfer of front & rear left door fittings and perform water seepage test. @ \$160.00	\$ 320.00 100

1,348.00
134.80
1,482.80

Policy No : SP2000440008
Date of Accident : 16 February 2022

Claims Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

Date : 21 February 2022

Estimate To Repair SMD585D - Toyota PRIUS PLUS (AUTO)
Chassis No : JTDZS3EU70J030203


S/No	Quantity	Description	Amount
05		<u>LABOUR & MISC. CHARGES</u> To check electrical wiring & lighting concerned.	\$ 80.00
			\$ 2,570.00
		Total	\$ 5,708.30

20
1,420
2,902.80

4 Days
P/P
before paint photos
excess TBA
not authorised
21/02/2022
Guo Qiang - LKK

LKK Auto Consultants hence notify
the Repairer of the following:
• To survey before/after spray painting
• To display damaged part(s) during survey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No legal modification(s) is allowed
• Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: TAN LIM MOTOR PTE LTD**

1 DEFULANE 6

SINGAPORE 539365

ATT: AH HWA

NO: DLI9248891

PAGE: 1

DATE: 21/02/2022

A/C CODE: LDTL178

TERMS: CR

P/O NO: SMD 585D

Part No	Description	Location	Qty	Unit Price	Amount
				<u>SIN</u>	<u>SIN</u>
1 T69210-74030-A0	FR DOOR OUTER HANDLE LH	DU1P52	1 ✓	140.00	140.00
2 T69250-74010-B0	FR DOOR OUTER HANDLE COVER LH	DDS ✓	1	18.00	18.00
3 T81740-52040	MIRROR LAMP LH	DD2H2-2 ✓	1	25.00	25.00
4 T42602-47090	HUB CAP	DU1X7	1 ✓	85.00	85.00
TOTAL QUANTITY:			4	TOTAL	SIN 268.00
				ADD GST @ 7%	18.76
				GRAND TOTAL	<u>SIN 286.76</u>

Print / YAM / 21/02/2022 1:22:14 PM


SALESMAN: YAM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY



合興汽車零件私人有限公司

HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

UEN No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: TAN LIM MOTOR PTE LTD**

1 DEFULANE 6

SINGAPORE 539365

ATT:AH HWA

NO: DLI9248873

PAGE: 1

DATE: 21/02/2022

A/C CODE: LDTL178

TERMS: CR

P/O NO: SMD 585D

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T67002-47111 /	FR DOOR LH	DB1G6	1	450.00	450.00
2 T67004-47180 /	RR DOOR LH	DB3017-6	1	420.00	420.00
3 T53802-47080 /	FR FENDER LH	DDS	1	210.00	210.00
TOTAL QUANTITY:			3	TOTAL	SIN 1,080.00
				ADD GST @ 7%	75.60
				GRAND TOTAL	<u>SIN 1,155.60</u>

Print / YAM / 21/02/2022 9:29:30 AM

SALESMAN: YAM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY

