

Policy No : SP2000440008
Date of Accident : 16 February 2022



1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Date : 21 February 2022

Estimate To Repair SMD585D - Toyota PRIUS PLUS (AUTO)

Chassis No : JTDZS3EU70J030203

S/No	Quantity	Description	Amount
		<u>Cost</u>	
01	1 pc	o/n front fender	\$ 195.00
02	1 pc	o/n inner fender cowl	\$ 85.00
03	1 pc	o/n front fender hybrid emblem	\$ 25.00
04	1 pc	o/n front fender wind deflector	\$ 35.00
05	1 pc	o/n front door	\$ 450.00
06	1 pc	o/n front door outer handle	\$ 140.00
07	1 pc	o/n front door outer handle extension	\$ 30.00
08	1 pc	o/n front door outer moulding	\$ 40.00
09	1 pc	o/n front door lock	\$ 240.00
10	1 pc	o/n front door power window motor	\$ 245.00
11	1 pc	o/n front door power window regulator	\$ 75.00
12	1 pc	o/n front door weather strip	\$ 60.00
13	1 pc	o/n side mirror cover	\$ 38.00
14	1 pc	o/n side mirror signal lamp	\$ 25.00
15	1 pc	o/n rear door	\$ 420.00
16	1 pc	o/n rear door outer moulding	\$ 40.00
17	1 pc	o/n rear door weather strip	\$ 60.00
18	1 pc	o/n rear fender	\$ 380.00
19	1 pc	o/n rear fender stickert	\$ 25.00
20	1 pc	o/n rear wheel cap	\$ 85.00
			\$ 2,693.00
		Add 10 %	\$ 269.30
			\$ 2,962.30
		<u>Cost</u>	
21	1 pc	o/n fender quater glass prime	\$ 80.00
22	1 pc	o/n fender quater glass sealant	\$ 80.00
			\$ 160.00
		Add 10 %	\$ 16.00
			\$ 176.00
		<u>LABOUR & MISC. CHARGES</u>	
01		Putty and spray painting on left side of the affected portion.	\$ 1,200.00
02		Panel beating, knocking and straighten on left side of the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 850.00
03		To rust-proofing of the affected areas.	\$ 120.00
04		To transfer of front & rear left door fittings and perform water seepage test. @ \$160.00	\$ 320.00

Policy No : SP2000440008
Date of Accident : 16 February 2022



1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Date : 21 February 2022

Estimate To Repair SMD585D - Toyota PRIUS PLUS (AUTO)

Chassis No : JTDZS3EU70J030203

S/No	Quantity	Description	Amount
05		<u>LABOUR & MISC. CHARGES</u>	
		To check electrical wiring & lighting concerned.	\$ 80.00
			\$ 2,570.00
		Total	\$ 5,708.30