

Policy No : SP2000440008
Date of Accident : 16 February 2022



1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Date : 21 February 2022

Estimate To Repair SMD585D - Toyota PRIUS PLUS (AUTO)

Chassis No : JTDZS3EU70J030203

S/No	Quantity	Description	Amount	
		<u>Cost</u>		
01	1 pc	N/S o/n front fender ✓ BT	\$ 195.00	210
02	1 pc	// o/n inner fender cowling X NN	\$ 85.00	
03	1 pc	// o/n front fender hybrid emblem ✓ NEG NN	\$ 25.00	
04	1 pc	// o/n front fender wind deflector X NN	\$ 35.00	
05	1 pc	// o/n front door ✓ BUC	\$ 450.00	✓
06	1 pc	// o/n front door outer handle ✓ CUT	\$ 140.00	✓
07	1 pc	// o/n front door outer handle extension ✓ CUT	\$ 30.00	18
08	1 pc	// o/n front door outer moulding X NN	\$ 40.00	
09	1 pc	// o/n front door lock X NN	\$ 240.00	
10	1 pc	// o/n front door power window motor X NN	\$ 245.00	
11	1 pc	// o/n front door power window regulator X NN	\$ 75.00	
12	1 pc	// o/n front door weather strip X NN	\$ 60.00	
13	1 pc	// o/n side mirror cover X Repair	\$ 38.00	
14	1 pc	// o/n side mirror signal lamp ✓ CRA	\$ 25.00	✓
15	1 pc	// o/n rear door ✓ BUC	\$ 420.00	✓
16	1 pc	// o/n rear door outer moulding X NN	\$ 40.00	
17	1 pc	// o/n rear door weather strip X NN	\$ 60.00	
18	1 pc	// o/n rear fender X Repair	\$ 380.00	
19	1 pc	// o/n rear fender stickert X NN	\$ 25.00	
20	1 pc	// o/n rear wheel cap ✓ CUT	\$ 85.00	✓
			\$ 2,693.00	1348
		Add 10 %	\$ 269.30	
			\$ 2,962.30	1482.8
		<u>Cost</u>		
21	1 pc	o/n fender quater glass prime X NN	\$ 80.00	
22	1 pc	o/n fender quater glass sealant X NN	\$ 80.00	
			\$ 160.00	
		Add 10 %	\$ 16.00	
			\$ 176.00	
		<u>LABOUR & MISC. CHARGES</u>		
01		Putty and spray painting on left side of the affected portion.	\$ 1,200.00	800
02		Panel beating, knocking and straighten on left side of the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 850.00	500
03		To rust-proofing of the affected areas.	\$ 120.00	X NN
04		To transfer of front & rear left door fittings and perform water seepage test. @ \$160.00	\$ 320.00	100

Policy No : SP2000440008
Date of Accident : 16 February 2022



1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Claims Department
Allianz Insurance Singapore Pte Ltd
79 Robinson Road #09-01
Singapore 068897

Date : 21 February 2022

Estimate To Repair SMD585D - Toyota PRIUS PLUS (AUTO)

Chassis No : JTDZS3EU70J030203

S/No	Quantity	Description	Amount
05		<u>LABOUR & MISC. CHARGES</u> To check electrical wiring & lighting concerned.	\$ 80.00
			\$ 2,570.00
		Total	\$ 5,708.30

20

2902.8

4 Days

P/P

before paint photos

excess TBA

not authorised

21/02/2022

Guo Qiang - LKK

LKK Auto Consultants hence notify the Repairer of the following: • To survey before/after spray painting • To display damaged part(s) during survey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--