

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0121/2022/ZK
DATE : 18-Feb-22
WIP :

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Dear Adrian,

3 days ok

OWNER'S NAME : MS LOU LINA
ADDRESS : 28 BUKIT BATOK EAST AVE
#25-03
SINGAPORE 659920
TELEPHONE : HP +65 81060624
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SNC 4815 H**
MODEL CODE : Q2 1.5 TFSI S
MODEL YEAR : 25/10/2021
ENGINE NO : DPC D27259
CHASSIS NO : WAUZZZGA1MA033733
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 13-Feb-22
PLACE OF ACCIDENT : CAR PARK AT LAUREL TREE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC 4815 H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	S/N \$	280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	\$	1,200.00	\$ 500.00
3	TO RESPRAY REAR BUMPER	\$	1,000.00	\$ 550.00
4	SUPPLEMENTARY	\$	2,400.00	\$ 525.00
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	5,072.00	\$ 2,047.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 4815 H

					DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT		REMARKS	
1	REAR BUMPER	1	\$	1,363.00	\$	1,090.40
2	REAR BUMPER ANTHRACITE TRIM - LH	1	\$	89.00	\$	71.04
3	REAR BUMPER TRIM - LH	1	\$	60.00	\$	47.92
4	SENSOR SUPPORT - LH OUTER	1	\$	25.00		
5	REAR LIGHT REFLECTOR - LH	1	\$	34.00	\$	26.48
6	REAR TAIL LIGHT - LH	1	\$	1,469.00	\$	1,175.20
7	REAR TAIL LIGHT TRIM - LH	1	\$	34.00		
8	REAR BUMPER CARRIER	1	\$	615.00		
9	REAR BUMPER HOLDING STRAP	1	\$	15.00		
10	REAR BUMPER GUIDE SECTION - LH	1	\$	60.00		
11	REAR PARKING AID SENSOR	1		TBC		
12	REAR PARKING AID SENSOR SEAL RING	4	\$	10.00		
13	REAR WHEEL ARCH COVER - LH / RH	2	\$	360.00	\$	287.20
14	SUPPLEMENTARY		\$	963.00	\$	769.92
15	SUNDRIES	1	\$	250.00		
TOTAL SPARE PARTS		:	\$	5,347.00	\$	3,468.16
TOTAL LABOUR CHARGES		:	\$	5,072.00	\$	2,047.00
GRAND TOTAL		:	\$	10,419.00	\$	5,515.16

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

BL-31/08/22



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0121/2022/ZK
Date 4-Apr-22
Service Advisor CHANG
Pages 1 of 1
Regn No SNC 4815 H
Model No AUDI Q2 1.5 TFSI

Quantity	Description		Unit Price	Amount
Labours				
1	TO REPAIR LHS TAIL LAMP PANEL.		\$ 800.00	\$ 250.00
2	TO RESPRAY LHS TAIL LAMP PANEL.		\$ 1,600.00	\$ 275.00
Parts				
1	REAR BUMPER LOWER SPOILER	1	\$ 927.00	\$ 741.20
2	REAR VENT TRIM - LH	1	\$ 36.00	\$ 28.72
GRAND TOTAL			\$ 3,363.00	\$ 1,294.92

For Premium Automobiles Pte Ltd

Authorised Signature