

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiuauto.com.sg / claims@premiuauto.com.sg




Supplementary Estimate-1

Xiao Chen.

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0121/2022/ZK 4-Apr-22 CHANG 1 of 1 SNC 4815 H AUDI Q2 1.5 TFSI
Quantity	Description	Unit Price	Amount
Labours			
1	TO REPAIR LHS TAIL LAMP PANEL.	\$ 800.00	250
2	TO RESPRAY LHS TAIL LAMP PANEL.	\$ 1,600.00	275
Parts			
1	REAR BUMPER LOWER SPOILER ^{cut}	\$ 927.00	✓
2	REAR VENT TRIM - LH ^{deformed}	\$ 36.00	✓
GRAND TOTAL		\$ 3,363.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling.
H.S.

Add 1 more day of repairs for
reshaping and to spray paint
the LHS Tail Lamp Panel.