

15 UBI ROAD 1, SINGAPORE 408690
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: MUMS@MIUMAUTOMOBILES.COM.SG TEAM@MIUMAUTOMOBILES.COM.SG

ESTIMATE : ACCIDENT REPAIRS
 WORKSHOP : UBI ROAD 1
 CONTACT NO : 6366 2323
 FAX NO : 6841 1183
 REFERENCE : PA/OD/0121/2022/ZK
 DATE : 18-Feb-22
 WIP : 12370

Xiao Chun.

\$ 5515.16.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
 Attn : Motor Claims Dept
 Tel: 6880 4602 - Fax: 6880 4838

03 Days

OWNER'S NAME : MS LOU LINA
 ADDRESS : 28 BUKIT BATOK EAST AVE
 #25-03
 SINGAPORE 659920
 TELEPHONE : HP +65 81060624
 TYPE OF CLAIM : OWN DAMAGE CLAIM
 POLICY NO :
 VEHICLE NO : SNC 4815 H
 MODEL CODE : Q2 1.5 TFSI S
 MODEL YEAR : 25/10/2021
 ENGINE NO : DPC D27259
 CHASSIS NO : WAUZZZGA1MA033733
 MILEAGE : -
 DATE IN : -
 ESTIMATED BY : JOHNNY BOO / ALLAN WU
 ACCIDENT DATE : 13-Feb-22
 PLACE OF ACCIDENT : CAR PARK AT LAUREL TREE

PREMIUM AUTOMOBILES



55 BRI ROAD 1, SINGAPORE 400639

TEL: 63662223 FAX: 68411183

EMAIL: WORK@PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNC48TS H

S/N	NATURE OF JOBS		ESTIMATED CHARGES	RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION	S/N \$	280.00	✓✓
2	TO DISMANTLE AND RENEW REAR BUMPER RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$	1,200.00 560	✓
3	TO RESPRAY REAR BUMPER	\$	1,000.00 550	✓
4	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 2,672.00</u>	

PREMIUM AUTOMOBILES



155 LIBERDADE J. SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NOOR KHAN@PREMIUMAUTO.COM.SG AP@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNC 4815 H

		DAMAGED PARTS & PRICES			
S/N	PARTS DESCRIPTION	QTY	UNIT	S/NETT	REMARKS
1	REAR BUMPER <i>De Land</i>	1	\$	2,290.00	✓ 1090.40
2	REAR BUMPER ANTHRACITE TRIM - LH <i>De Land</i>	1	\$	89.00	✓ 71.04
3	REAR BUMPER TRIM - LH <i>De Land</i>	1	\$	60.00	✓ 47.92
4	SENSOR SUPPORT - LH OUTER <i>new</i>	1	\$	25.00	+
5	REAR LIGHT REFLECTOR - LH <i>cut</i>	1	\$	34.00	✓ 26.48
6	REAR TAIL LIGHT - LH <i>cracked</i>	1	\$	1,469.00	✓ 1175.20
7	REAR TAIL LIGHT TRIM - LH <i>new</i>	1	\$	34.00	+
8	REAR BUMPER CARRIER <i>Not nec</i>	1	\$	615.00	+
9	REAR BUMPER HOLDING STRAP <i>Not nec</i>	1	\$	15.00	✗
10	REAR BUMPER GUIDE SECTION - LH <i>Not nec</i>	1	\$	60.00	+
11	REAR PARKING AID SENSOR <i>Not nec</i>	1		TBC	+
12	REAR PARKING AID SENSOR SEAL RING <i>Not nec</i>	4	\$	10.00	+
13	REAR WHEEL ARCH COVER - LH / RH <i>Not nec</i>	2	\$	360.00	✓ 287.20
14	<i>Sundries Not nec.</i>			250.00	✗
TOTAL SPARE PARTS		:	\$	5,311.00	
TOTAL LABOUR CHARGES		:	\$	2,672.00	
GRAND TOTAL		:	\$	<u>7,983.00</u>	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD #, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

Adnan
18/02/22

Not Authorised, 03 Days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT