

Claim Audit

AUDIT TRAIL

No.	On	Audit	Remarks	By
1	17 Feb 2022 19:35	Clm Veh Model Changed		[] Merimen Administrator
2	17 Feb 2022 19:35	Clm Created	Reg No: SKW9975B. Policy No: 2100439266-06. Acct Date: 2022/02/16. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:SP0R222H0002	[I] Merimen Administrator
3	21 Feb 2022 12:30	Clm Registration Modified	Setl.Type:3->0. Claim Type:SC->OD.	[] NA MENG YAN
4	21 Feb 2022 12:30	Adj Clm Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[] NA MENG YAN
5	21 Feb 2022 12:30	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] NA MENG YAN
6	21 Feb 2022 12:30	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/03/02	[A] NA MENG YAN
7	21 Feb 2022 12:30	Adj Mandate Set	Approved:0.00.Reinsp:Adj decides.	[A] NA MENG YAN
8	21 Feb 2022 12:30	Clm Registration Modified	Rep:1137->200611.	[A] NA MENG YAN
9	21 Feb 2022 12:30	Clm Veh Model Changed	(204651) AUDI A6 1.8 TFSI Ultra (PI) (NAV) (A).	[A] NA MENG YAN
10	21 Feb 2022 12:30	Adj Adjuster Assigned	[None] -> ADRIAN LING	[A] NA MENG YAN
11	21 Feb 2022 14:27	Adj Rpt Initiated		[A] HUEY YON
12	21 Feb 2022 14:27	Clm Dtl Modified	Claim Conclusion: -> 3.	[A] HUEY YON
13	21 Feb 2022 14:27	Clm Dtl Modified	JPJ Reg. Date: -> 2015/11/24.	[A] HUEY YON
14	21 Feb 2022 14:27	Clm Details Notified		[A] HUEY YON
15	22 Feb 2022 10:04	Clm Registration Modified	Init.Est.:->5,000 - 6,000. Excess: -> 800.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Loo, Tong Shing
16	22 Feb 2022 14:14	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/03/02	[A] SHIAU CHAN

AUDIT TRAIL

No.	On	Audit	Remarks	By
17	22 Feb 2022 14:15	Adj Mandate Request	Cur.Req:50426.00:DAMAGES CONSISTENT. PENDING REPAIR COST FROM REPAIRER. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	22 Feb 2022 18:33	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2022/03/02. Mandate Remarks: Vehicle may commence repair - To set repair limit of \$25,900 ONLY to repairer and confirm if they are able to undertake the repair. Checked and Supplementary items to resurvey with CLEAR p	[I] Lim, Kok-Chong
19	22 Feb 2022 18:33	Adj Mandate Set	Approved:25900.00:Vehicle may commence repair - To set repair limit of \$25,900 ONLY to repairer and confirm if they are able to undertake the repair. Checked and Supplementary items to resurvey with CLEAR photos for damage and consistency.	[I] Lim, Kok-Chong
20	22 Mar 2022 17:54	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2022/03/02	[A] SHIAU CHAN
21	22 Mar 2022 17:55	Adj Mandate Request	Cur.Req:38785.00:Please note that the owner will top up the balance if the repair cost exceed \$25,900.00 as approved.	[A] SHIAU CHAN
22	22 Mar 2022 19:15	Adj Next Rpt Changed	Cur Rpt:Final Rpt. Cur Due Date:2022/03/02. Mandate Remarks: Repair limit of \$25,900 ONLY.	[I] Lim, Kok-Chong
23	22 Mar 2022 19:15	Adj Mandate Set	Approved:25900.00:Repair limit of \$25,900 ONLY.	[I] Lim, Kok-Chong

Date From



Date To



Audit Type

None



Go

ACTIVITY

[22/02/2022 14:15] SHIAU CHAN:
PENDING REPAIR COST FROM REPAIRER.

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2767430	21 Feb 2022 14:27:48	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	SKW9975B		11.00