

# PREMIUM AUTOMOBILES

000

100 ROAD, SINGAPORE 308550  
TEL: 6463323 FAX: 65411185  
E-MAIL: [premium@com.sg](mailto:premium@com.sg) / CLAIMS@PREMIUMAUTO.COM

SKW9975

Xiao Chan.

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKW 9975 B

| S/N                  | NATURE OF JOBS                                                                                                                                               | ESTIMATED CHARGES            | SURVEYOR'S RECOMMENDATIONS |
|----------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|----------------------------|
| 1                    | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.             | S/N \$ 480.00                | ✓                          |
| 2                    | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                                        | S/N \$ <del>400.00</del> 250 | ✓                          |
| 3                    | TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACCUM AND REGAS. | S/N \$ 1,700.00              | ✓                          |
| 4                    | TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.                                                                                           | S/N \$ 2,800.00              | ✓                          |
| 5                    | TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.                                                                                                               | S/N \$ 800.00                | ?                          |
| TOTAL LABOUR CHARGES |                                                                                                                                                              | : \$ <u>6,180.00</u>         |                            |

Adrian Li  
Resurveyed.  
21/03/22. *sls*



WELCOME TO PLATINUM

# PLATINUM AUTOMOBILES

00

1000 ROAD, SINGAPORE 0804  
TEL: 672155 FAX: 64411153  
E-MAIL: info@platinumcars.com.sg

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKW 9975 B

| S/N                  | NATURE OF JOBS                                                                                                                                                                                                                                           | ESTIMATED CHARGES           | SURV'S RECOMMENDATIONS |
|----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|------------------------|
| 6                    | TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.                                                                                                                                                                                            | S/N \$ 2,400.00             | ?                      |
| 7                    | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED | \$ <del>8,000.00</del> 2000 | +1250 - R.S.           |
| 8                    | TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, X BONNET, LHS FRONT FENDER TOP SUPPORT, LHS FRONT DOOR AND LHS UPPER A-PILLAR.                                                                                                                                | \$ <del>6,000.00</del> 2750 |                        |
| 9                    | TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.                                                                                                                                                                                           | S/N \$ 520.00               | ✓                      |
| 10                   | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK                                                                                                                                                                                                                   | S/N \$ 384.00               | ✓                      |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                                                                                          | : \$ <u>23,484.00</u>       |                        |



# PREMIUM AUTOMOBILES

5 LBI ROAD 1, SINGAPORE 406999

Tel: 6342 2323 Fax: 6342 1183

100% GENUINE PARTS & SERVICES. MAINTENANCE & CLAIMS OF REMAINING. QUALITY ASSURED.

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW3375S

| S/N                   | PARTS DESCRIPTION                                     | QTY | DAMAGED PAI | S/NETT                   |
|-----------------------|-------------------------------------------------------|-----|-------------|--------------------------|
| 41                    | HEADLIGHT MATRIX BEAM - LH <i>Smashed</i>             | 1   | \$          | 13,172.00 ✓              |
| 42                    | SIGNAL LIGHT POWER MODULE ?                           | 1   | \$          | 611.00 ?                 |
| 43                    | DIPPED BEAM POWER MODULE ?                            | 1   | \$          | 625.00 ?                 |
| 44                    | HEADLIGHT MATRIX POWER MODULE ?                       | 1   | \$          | 2,121.00 ?               |
| 45                    | HEADLIGHT HOSE - LH <i>new</i>                        | 1   | \$          | 40.00 ✓                  |
| 46                    | HEADLAMPS FAN - LH ?                                  | 1   | \$          | 428.00 ?                 |
| 47                    | HEADLIGHT ADJUSTMENT ELEMENT ?                        | 1   | \$          | 51.00 ?                  |
| 48                    | SPACER ?                                              | 2   | \$          | 92.00 ?                  |
| 49                    | LIFT CYLINDER - LH ?                                  | 1   | \$          | 259.00 ?                 |
| 50                    | LIFT CYLINDER HOSE ?                                  | 1   | \$          | 553.00 ?                 |
| 51                    | LOCK CARRIER <i>crushed</i>                           | 1   | \$          | 1,385.00 ✓ <i>3 H.S.</i> |
| 52                    | RADIATOR COOLANT <i>new</i>                           | ①   | \$          | 282.00 ✓                 |
| 53                    | RADIATOR AIR GUIDE - LH <i>new</i>                    | 1   | \$          | 86.00 ✓                  |
| 54                    | RADIATOR AIR GUIDE UPPER CENTER COVER <i>new</i>      | 1   | \$          | 32.00 ✓                  |
| 55                    | FRONT FENDER TOP SUPPORT - LH UPPER <i>Distorted</i>  | 1   | \$          | 841.00 ✓                 |
| 56                    | NOISE INSULATION PLATE - LH <i>end</i>                | 1   | \$          | 37.00 ✓ <i>2 H.S.</i>    |
| 57                    | FRONT FENDER TOP SUPPORT - LOWER UPPER <i>crushed</i> | 1   | \$          | 326.00 ✓                 |
| 58                    | WATER DEFLECTOR STRIP - LH <i>new</i>                 | 1   | \$          | 75.00 ✓                  |
| 59                    | ROOF CHROME MOULDING - LH <i>new</i>                  | 1   | \$          | 571.00 ✓                 |
| 60                    | FRONT WINDOW SLOT SEAL TRIM STRIP - LH <i>new</i>     | 1   | \$          | 380.00 ✓                 |
| SUB TOTAL SPARE PARTS |                                                       | :   | \$          | 21,967.00                |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES

1000 PLAD 1, SMG-PURE 408695

TEL: 0366 2373 FAX: 0361 1163

WWW.PREMIUMAUTO.COM.SG CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 9975 S

| S/N                  | PARTS DESCRIPTION                           | QTY | S/NETT       | DAMAGED PARTS & PHOTOS |
|----------------------|---------------------------------------------|-----|--------------|------------------------|
| 61                   | ALUMINIUM RIM <i>RH n</i>                   | 1   | \$ 1,847.00  | X                      |
| 62                   | RUBBER VALVE <i>NH n</i>                    | 4   | \$ 15.00     | X                      |
| 63                   | WISHBONE LINK - LH <i>Best</i>              | 1   | \$ 605.00    | <i>2 } H.S.</i>        |
| 64                   | WISHBONE SUSPENSION GUIDE <i>Best</i>       | 1   | \$ 1,095.00  |                        |
| 65                   | FRONT UPPER ARM - LH FRONT ?                | 1   | \$ 605.00    | ?                      |
| 66                   | FRONT UPPER ARM - LH REAR ?                 | 1   | \$ 605.00    | ?                      |
| 67                   | WHEEL BEARING HOUSING - LH ?                | 1   | \$ 1,256.00  | ?                      |
| 68                   | WISHBONE SWIVEL JOINT <i>Best</i>           | 1   | \$ 191.00    | <i>2</i>               |
| 69                   | WISHBONE WHEEL HUB <i>Best</i>              | 1   | \$ 518.00    | <i>2</i>               |
| 70                   | WHEEL BEARING ASSEMBLY PARTS <i>Best</i>    | 1   | \$ 570.00    | <i>2</i>               |
| 71                   | SUSPENSION FORKS - LH ?                     | 1   | \$ 263.00    | ?                      |
| 72                   | COUPLING ROD ?                              | 2   | \$ 258.00    | ?                      |
| 73                   | ANTI-ROLL BAR ?                             | 1   | \$ 548.00    | ?                      |
| 74                   | GAS SHOCK ABSORBER ?                        | 1   | \$ 628.00    | ?                      |
| 75                   | DRIVE SHAFT VELOCITY JOINT - LH <i>RH n</i> | 1   | \$ 3,239.00  | X                      |
| 76                   | TRACK ROD <i>Best</i>                       | 1   | \$ 109.00    | <i>2 } H.S.</i>        |
| 77                   | TIE ROD END - LH <i>Best</i>                | 1   | \$ 195.00    | <i>2</i>               |
| 78                   | FRONT NO PLATE <i>NH n</i>                  | S/N | \$ 60.00     | X                      |
| 79                   | ARYLIC SEALANT <i>2</i>                     | S/N | \$ 180.00    | <i>2</i>               |
| 80                   | CAVITY WAX <i>NH</i>                        | S/N | \$ 140.00    | <i>✓</i>               |
| 81                   | STONE CHIP                                  | S/N | \$ 180.00    | <i>✓</i>               |
| 82                   | METAL FILLER POWDER                         | S/N | \$ 280.00    | <i>✓</i>               |
| 83                   | SUNDRIES                                    |     | \$ 600.00    |                        |
| TOTAL SPARE PARTS    |                                             | :   | \$ 55,346.00 |                        |
| TOTAL LABOUR CHARGES |                                             | :   | \$ 23,484.00 |                        |
| GRAND TOTAL          |                                             | :   | \$ 78,830.00 |                        |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.