# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.

Ltd.

AIG Building, 78 Shenton Way

#09-16

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park

Singapore 408933

Date: 22 Feb 2022 Attn: Loo, Tong Shing

# **Preliminary Advice**

Vehicle No : SKW9975B Accident Date : 16/02/2022 : AUDI A6 Policy No. Make : 2100439266-

06

: 8

Assignment

Date

: 21/02/2022

Excess

: S\$800.00

Date of : 18/02/2022

Est. Duration of

Repair

Inspection

Inspection At: PREMIUM AUTOMOBILES PTE LTD (UBI)

55 UBI ROAD 1

SINGAPORE 408699

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 78,830.00 **Revised Amount** :S\$ 27,349.00 :S\$ 23,077.00 Check Items (Estimated) :S\$ 50,426.00 Total

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

:S\$ 81,000.00 Pre-Accident Value COE / PARF Rebate :S\$ 55.063.00

Salvage Value :S\$

## Remarks

(	) The vehicle is repairable at our adjusted amount. We have also confirmed
	excess and policy coverage. Kindly let us have your authorisation.

( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

( X ) Other comments : PENDING REPAIR COST FROM REPAIRER.

Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.