

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0120/2022/JT
DATE : 17-Feb-22
WIP : 12166

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

We took 17 days of repair.

OWNER'S NAME : M/S INTERNATIONAL FIBRE RESOURCES PTE LTD
ADDRESS : 10 ANSON ROAD
#20-03A INTERNATIONAL PLAZA
SINGAPORE 079903
TELEPHONE : HP +65 92305390
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100439266-06
VEHICLE NO : **SKW 9975 B**
MODEL CODE : AUDI A6 1.8 TFSI ULTRA S
MODEL YEAR : 24/11/2015
ENGINE NO : CYG 004888
CHASSIS NO : WAUZZZ4GXFN083339
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Feb-22
PLACE OF ACCIDENT : INTERNATIONAL PLAZA CAR PARK EXIT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKW 9975 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. TO CARRY OUT PRESSURISE, VACCUM AND REGAS.	S/N \$	1,700.00	\$	1,700.00
4	TO REMOVE AND RENEW LHS FRONT WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$	2,800.00	\$	2,800.00
5	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER.	S/N \$	800.00		
TOTAL LABOUR CHARGES		:	\$ 6,180.00	\$	5,230.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKW 9975 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 5,230.00
6	TO SETUP THE VEHICLE ON CAR O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	
7	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER, BONNET AND LHS HEADLIGHT. TO CUT OUT AND WELD LHS FRONT FENDER TOP SUPPORT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 8,000.00	\$ 3,250.00
8	TO RESPRAY FRONT BUMPER, LHS FRONT FENDER, BONNET, LHS FRONT FENDER TOP SUPPORT, LHS FRONT DOOR AND LHS UPPER A-PILLAR.	\$ 6,000.00	\$ 2,750.00
9	TO RENEW LHS FRONT RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	\$ 520.00
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	\$ 384.00
TOTAL LABOUR CHARGES		: \$ 23,484.00	\$ 12,134.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 9975 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,012.00	\$ 2,409.60
2	FRONT BUMPER GRILLE	1	\$ 739.00	
3	LOCKING CLIP	18	\$ 78.00	
4	FRONT BUMPER CHROME TRIM	1	\$ 340.00	
5	FRONT BUMPER FIXING PARTS	1	\$ 54.00	
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 237.00	
7	FRONT BUMPER SPOILER	1	\$ 276.00	
8	RADIATOR GRILLE	1	\$ 2,140.00	
9	RADIATOR GRILLE COVER	1	\$ 41.00	
10	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 393.00	\$ 314.00
11	FRONT BUMPER AIR GUIDE GRILLE COVER - LH	1	\$ 58.00	
12	FRONT WHEEL SPOILER - LH	1	\$ 294.00	\$ 234.80
13	LIFT CYLINDER CAP COVER	1	\$ 64.00	
14	FRONT BUMPER FOAM FILLER PIECE	1	\$ 265.00	
15	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 927.00	
16	FRONT BUMPER GUIDE PIECE - LH	1	\$ 42.00	\$ 33.12
17	FRONT BUMPER BRACE - LH	1	\$ 34.00	
18	FRON BUMPER TOP COVER	1	\$ 137.00	\$ 109.60
19	CAUTION STICKER	1	\$ 16.00	\$ 12.40
20	AIR COND STICKER	1	\$ 34.00	\$ 26.96
SUB TOTAL SPARE PARTS		:	\$ 9,181.00	\$ 3,140.48

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 9975 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	3,140.48
21	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 488.00		
22	FRONT PARKING AID SENSOR SIDE	1	\$ 244.00		
23	FRONT PARKING AID SENSOR SEAL RING	6	\$ 9.00		
24	FRONT BUMPER WIRING	1	\$ 642.00		
25	HORN - LH	1	\$ 214.00		
26	HORN SUPPORT - LH	1	\$ 53.00		
27	FRONT FENDER - LH	1	\$ 1,560.00	\$	1,248.00
28	FRONT FENDER ATTACHMENT PARTS	1	\$ 107.00	\$	85.60
29	FRONT FENDER STONE GUARD FILM - LH	1	\$ 135.00	\$	108.00
30	FRONT FENDER BRACE - LH	1	\$ 107.00	\$	85.60
31	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 60.00	\$	47.28
32	FRONT FENDER SEAL - LH	1	\$ 23.00	\$	17.92
33	FRONT FENDER SEALING ELEMENT - LH	1	\$ 45.00	\$	35.36
34	FRONT WHEEL HOUSING LINER - LH	1	\$ 310.00	\$	248.00
35	FRONT FENDER STONE CHIP GUARD - LH	1	\$ 82.00		
36	FRONT FENDER ADHESIVE TAPE	1	\$ 59.00	\$	47.20
37	FRONT FENDER TRIM BRACKET - LH	1	\$ 19.00		
38	BONNET	1	\$ 5,736.00		
39	BONNET ATTACHMENT PARTS	1	\$ 186.00		
40	HEADLIGHT MOUNTING - LH	1	\$ 132.00	\$	105.20
SUB TOTAL SPARE PARTS		:	\$ 10,211.00	\$	5,168.64

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 9975 B

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	5,168.64
41	HEADLIGHT MATRIX BEAM - LH	1	\$ 13,172.00	\$	10,537.60
42	SIGNAL LIGHT POWER MODULE	1	\$ 611.00		
43	DIPPED BEAM POWER MODULE	1	\$ 625.00		
44	HEADLIGHT MATRIX POWER MODULE	1	\$ 2,121.00		
45	HEADLIGHT HOSE - LH	1	\$ 40.00		
46	HEADLAMPS FAN - LH	1	\$ 428.00		
47	HEADLIGHT ADJUSTMENT ELEMENT	1	\$ 51.00		
48	SPACER	2	\$ 92.00		
49	LIFT CYLINDER - LH	1	\$ 259.00		
50	LIFT CYLINDER HOSE	1	\$ 553.00		
51	LOCK CARRIER	1	\$ 1,385.00	\$	1,108.00
52	RADIATOR COOLANT	6	\$ 282.00	\$	225.60
53	RADIATOR AIR GUIDE - LH	1	\$ 86.00		
54	RADIATOR AIR GUIDE UPPER CENTER COVER	1	\$ 32.00		
55	FRONT FENDER TOP SUPPORT - LH UPPER	1	\$ 841.00	\$	672.80
56	NOISE INSULATION PLATE - LH	1	\$ 37.00	\$	29.12
57	FRONT FENDER TOP SUPPORT - LOWER UPPER	1	\$ 326.00	\$	260.80
58	WATER DEFLECTOR STRIP - LH	1	\$ 75.00		
59	ROOF CHROME MOULDING - LH	1	\$ 571.00		
60	FRONT WINDOW SLOT SEAL TRIM STRIP - LH	1	\$ 380.00		
SUB TOTAL SPARE PARTS		:	\$ 21,967.00	\$	18,002.56

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKW 9975 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		c/f		\$	18,002.56
61	ALUMINIUM RIM	1 \$	1,847.00		
62	RUBBER VALVE	4 \$	15.00		
63	WISHBONE LINK - LH	1 \$	605.00	\$	483.60
64	WISHBONE SUSPENSION GUIDE	1 \$	1,095.00	\$	876.00
65	FRONT UPPER ARM - LH FRONT	1 \$	605.00		
66	FRONT UPPER ARM - LH REAR	1 \$	605.00		
67	WHEEL BEARING HOUSING - LH	1 \$	1,256.00		
68	WISHBONE SWIVEL JOINT	1 \$	191.00	\$	152.80
69	WISHBONE WHEEL HUB	1 \$	518.00	\$	414.40
70	WHEEL BEARING ASSEMBLY PARTS	1 \$	570.00	\$	455.60
71	SUSPENSION FORKS - LH	1 \$	263.00		
72	COUPLING ROD	2 \$	258.00		
73	ANTI-ROLL BAR	1 \$	548.00		
74	GAS SHOCK ABSORBER	1 \$	628.00		
75	DRIVE SHAFT VELOCITY JOINT - LH	1 \$	3,239.00		
76	TRACK ROD	1 \$	109.00	\$	87.20
77	TIE ROD END - LH	1 \$	195.00	\$	155.60
78	FRONT NO PLATE	S/N \$	60.00		
79	ARYLIC SEALANT	S/N \$	180.00	\$	180.00
80	CAVITY WAX	S/N \$	140.00	\$	140.00
81	STONE CHIP	S/N \$	180.00	\$	180.00
82	METAL FILLER POWDER	S/N \$	280.00	\$	280.00
83	SUPPLEMENTARY	\$	45.00	\$	35.92
84	SUNDRIES	\$	600.00	\$	14.56
TOTAL SPARE PARTS		:	\$ 55,391.00	\$	21,458.24
TOTAL LABOUR CHARGES		:	\$ 23,484.00	\$	12,134.00
GRAND TOTAL		:	\$ 78,875.00	\$	33,592.24

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-26/05/22



55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No. PA/OD/0120/2022/JT
Date 5-Mar-22
Service Advisor CHANG
Pages 1 of 1
Regn No SKW 9975 B
Model No AUDI A6 1.8 TFSI ULTRA

Quantity	Description	Unit Price	Amount
Parts			
1	HEADLIGHT WASHER PIPE	\$ 45.00	\$ 35.92
GRAND TOTAL		\$ 45.00	\$ 35.92

For Premium Automobiles Pte Ltd

Authorised Signature