

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0103/2022/JT
DATE : 15-Feb-22
WIP : 11617

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 16/2/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

5 days ok - Carrine

OWNER'S NAME : MR YAP EWE JIN BENEDICT (YE YAOJUN)
ADDRESS : BLK 4 LORONG M TELOK KURAU
#03-04
SINGAPORE 425283
TELEPHONE : HP +65 96389069
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100400488-06
VEHICLE NO : **SKR 5186 P**
MODEL CODE : AUDI A3 SEDAN 1.4 TFSI
MODEL YEAR : 12/2/2015
ENGINE NO : CZC 218094
CHASSIS NO : WAUZZZ8V6F1057644
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 15-Feb-22
PLACE OF ACCIDENT : 4 LORONG M TELOK KURAU CAR PARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKR 5186 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$	280.00	\$	280.00
2	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00		
3	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	\$	280.00
4	TO DISMANTLE AND RENEW LHS REAR DOOR. TO DISMANTLE REAR BUMPER TO REPAIR LHS REAR FENDER AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,800.00	\$	1,000.00
5	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, LHS SILL PANEL, LHS REAR FENDER AND REAR BUMPER.	\$	4,200.00	\$	1,650.00
6	TO RENEW LHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 8,382.00	\$	3,682.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKR 5186 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - LH	1	\$ 3,265.00	\$ 2,612.00
2	REAR DOOR BUNGS - LH	1	\$ 5.00	
3	REAR DOOR OUTER SEAL - LH	1	\$ 179.00	\$ 142.80
4	BONDING AGENT	1	\$ 51.00	
5	CLEANING SOLUTION	1	\$ 74.00	
6	APPLICATOR	1	\$ 8.00	
7	REAR DOOR CATCH - LH	1	\$ 23.00	
8	REAR DOOR ATTACHMENT PARTS	1	\$ 134.00	
9	REAR WHEEL SPOILER - LH	1	\$ 39.00	
10	REAR SILL PANEL COVER - LH	1	\$ 4.00	
11	REAR WHEEL HOUSING LINER	1	\$ 260.00	
12	ALUMINIUM RIM	1	\$ 1,303.00	\$ 1,042.40
13	RUBBER VALVE	4	\$ 15.00	
34	STONE CHIP	S/N	\$ 180.00	
	SUNDRIES		\$ 350.00	\$ 6.56
TOTAL SPARE PARTS		:	\$ 5,890.00	\$ 3,803.76
TOTAL LABOUR CHARGES		:	\$ 8,382.00	\$ 3,682.00
GRAND TOTAL		:	\$ 14,272.00	\$ 7,485.76

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl-25/04/22