## PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511 CO. REG:200707743D GST REG:200707743D

21-Feb-22

ESTIMATE REPAIR BILL	FOR KIA OPTIMA	A REGN NO: SHIB 8	043 T
----------------------	----------------	-------------------	-------

LOTIMATE	KEI AIR BILL I GITTIBLE I		100000000000000000000000000000000000000		
1 pc	Rear bumper			\$	696.00 de
1 pc	Rear bumper lower cover			\$	206.00 de
2 pcs	Rear bumper side bracket o/s & n/s			\$	58.00 ×
1 pc	Rear bumper inner sponge			\$	114.00
1 pc	Rear bumper reinforcement			\$	607.00
2 pcs	Rear bumper stay o/s & n/s @\$53			\$	106.00 (
2 pcs	Rear bumper reinforcement lower bracket @ \$18.0		<b>)</b>	\$	36.00 ⋉
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00			\$	36.00 ×
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00			\$	92.00 ×
				\$	1,951.00
			Less 10%	\$	195.10
				\$	1,755.90
		LKK Auto Consultants the Repairer of the fo • To resurvey before/after	lowing:		
S/NETT	- December of the	<ul> <li>To display damaged part</li> </ul>	s) during resurvey	\$	48.00 × 280.00 × ?
1 set	Rear bumper clips	<ul> <li>Parts prices are subject to</li> <li>Third party survey is on a</li> </ul>		\$	30.00 ×
1 set	End panel inner garnish clips	<ul> <li>No illegal modification(s)</li> </ul>	s allowed	\$	280.00 200?
1 set	Reverse sensor	<ul> <li>Supplementary item(s) m is subject to final approva</li> </ul>	from Insurance Company	Ψ	200.00
	Sundry	Acknowledged by Repairer Signature:		\$	50.00
	To dismantle / replace reverse sensor to new bumpereset to the same  To dismantle / refit the inner garnishes, inner linings trims, cushion seat, carpet, etc to facilitate repairs.		r and	\$	120.00 30
			inner	\$	180.00 ×
	To labour charge for dismantle and renew the acciden damaged parts. Including knock-out, straighten, repair reshape and adjust of the end panel		ent air,	\$	750.00 Zoo
	To putty and spray painting on rear bumper, end par		nel	\$	400.00 200
	To apply rustproofing on the repaired and replaced r		panels.	\$	80.00 × 3,693.90
	( ALL THE REPAIR COSTS A	RE SUBJECTED TO	GST) N	jihn P 2	97415749

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

\$ 3,693.90 Taufilm 97415747 WP 21/2/22 8330 2 days 2/5 Resun app epon taufum e/hhautim