

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

21-Feb-22

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8043 T

1 pc	Rear bumper	\$	696.00	dl
1 pc	Rear bumper lower cover	\$	206.00	dl
2 pcs	Rear bumper side bracket o/s & n/s	\$	58.00	x
1 pc	Rear bumper inner sponge	\$	114.00	2
1 pc	Rear bumper reinforcement	\$	607.00	2
2 pcs	Rear bumper stay o/s & n/s @\$53	\$	106.00	2
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00	\$	36.00	x
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00	\$	36.00	x
2 pcs	Rear bumper reflector n/s & o/s @ \$46.00	\$	92.00	x
		\$	1,951.00	902
		Less 10%	\$	195.10
			\$	1,755.90

S/NETT

1 set	Rear bumper clips	\$	48.00	30ue
1 set	End panel inner garnish clips	\$	30.00	x n
1 set	Reverse sensor	\$	280.00	200 x n
	Sundry	\$	50.00	30 x n
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	x n.
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel	\$	750.00	200
	To putty and spray painting on rear bumper, end panel	\$	400.00	200
	To apply rustproofing on the repaired and replaced panels.	\$	80.00	x n
		\$	3,693.90	430

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

1271.80

1/5/1000

2 days

Tanphn 97415749

WP' 21/2/22 @ 330

2 days

1/5 Resurvey after repair
tanphn @ 1/10/2020