

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 26 Feb 2022

Preliminary Advice

Insured Vehicle No : YN9697K
TP Vehicle No : SMM1810A
Make : HONDA FIT
Date of Inspection : 21/2/2022
Inspection At : ZOOM AUTOWERKS PTE LTD

Accident Date : 18/02/2022
Assignment Date : 21/02/2022
Est. Duration of Repair : 3

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,217.04
Revised Amount	:S\$	1,636.16
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,636.16
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	68,000.00
COE / PARF Rebate	:S\$	24,011.00
Salvage Value	:S\$	
Margin for Repair	:S\$	43,989.00

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 (X) Part-by-Part repair
 () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.

. Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost .