|              | HSIAU ZOM   | ,                      |
|--------------|---|------------------------|
| 7            | FASTECH AUTO PTE LTD                                  | NOT Arbord             |
| 40           | 1 Kaki Bukit Ave 6 #01-48 Autobay                     | Lu                     |
|              | Singapore 417883                                      | 22/1/22                |
|              | Tel No: 67452063/ 67467158 Fax No: 67458520           | 10/0/00                |
|              | Tax Reg No : 200006262D                               | 2/4 = 5300             |
|              | 10x 11cg 110 . 200000202D                             | 1-11                   |
|              | VEHICLE No: SLH 2735R                                 | 5 dys.                 |
| 1PC          | DEAD WINDSCREEN                                       |                        |
| 1PC          | REAR WINDSCREEN A 1 REAR WINDSCREEN MOULDING          | \$1,288.10 🗡           |
| 1PC          | TAHCATE   | \$145.40               |
| 1PC          | TAILGATE OUTER HANDLE                                 | \$1,742.00             |
| 2PCS         | TAILGATE REFLECTORS @\$182.40                         | \$299.40 X             |
| 1PC          | TAILGATE INNER LOCK 05/5holl 416 for                  | \$364.80 🗶             |
| 1PC          | TAILGATE WEATHERSTRIP (W) 322.30                      | \$616.80               |
| 1PC          | TAILGATE INNER TRIM BOARD De 17010 481.10             | \$386.20               |
| 1PC          | REAR BUMPER DD 596.93                                 | \$767.30               |
| 2PCS         | REAR BUMPER DAMPERS @\$85.00                          | \$665.90               |
| 2PCS         | REAR BUMPEER SIDE RETAINERS @\$65.00 1                | \$170.00 ×<br>\$130.00 |
| 2PCS         | REAR BUMPER REFLECTORS @\$60.00 , 1 1                 | \$120.00 ×             |
| 1PC          | REAR END PANEL OUTER Solson / But 542.00              | \$842.00               |
| 1PC          | REAR END PANEL LOWER                                  | \$389.20 ×             |
| 1PC          | REAR END PANEL TOP GARNISH                            | \$381.80               |
| 2PCS         | TAILLAMPS @\$395.00                                   | \$790.00 ×             |
| 2PCS         | REAR FENDER INNER TRIM BOARDS @\$781.10 3/5 De / Tour | \$1,562.20(2)          |
| 1PC          | REAR FENDER UNDER SHIELD O/S 🔥 🦶                      | \$121.50 X             |
| 1PC          | REAR FLOOR PANEL REAR FLOOR PANEL                     | \$1,410.80 X           |
| 1PC          | REAR ANTENNA SENSOR                                   | \$281.50               |
| 1PC          | REAR SPARE TYRE LOCK CARRIER NA 257                   | \$395.00 🗙             |
|              | CALE  | \$12,869.90            |
|              | S.NETT  |                        |
| 1PC          | REAR LICENCE PLATE SU                                 | \$50.00 🗴              |
| 1PC          | REAR WINDSCREEN SEALANT 1                             | \$50.00 40             |
| 1PC          | REAR WINDSCREEN INNER SEAL 1                          | \$50.00 40             |
| 1SET         | TAILGATE INNER TRIM BOARD CLIPS 1                     | \$50.00                |
| 1PC          | TAILGATE 'BORNEO' LOGO                                | \$60.00                |
| 1SET         | REAR BUMPER CLIPS                                     | \$50.00                |
| 1SET         | REAR BUMPER REVERSE SENSOR                            | \$280.00 200           |
| 1SET         | REAR REVERSE CAMERA                                   | \$450.00 X             |
| 1SET<br>1SET | REAR FENDER INNER TRIM BOARD CLIPS MA                 | \$50.00 🗶              |
| 1SET         | REAR FENDER UNDER SHIELD CLIPS O/S                    | \$30.00 🗶              |
| 1361         | REAR FLOOR PANEL INSULATOR                            | \$180.00               |
|              | TO CHECK WIRING                                       | \$50.00 20             |
|              | TO REMOVE & REPLACED REAR REVERSE SENSOR              | \$80.00                |
|              | TO REMOVE & REFIX REAR WINDSCREEN                     | \$150.00 1 20          |
|              | TO REMOVE & REFIX TAILGATE MECHANISM                  | \$100.00 60            |
|              | TO REMOVE & REFIX CUSHION UPHOLSTERY                  | \$120.00               |
|              | TO REMOVE & REFIX REAR EXHAUST                        | √^ \$100.00 X          |
|              |   |                        |

TO REMOVE & REFIX FUEL TANK TO REMOVE & REFIX REAR REVERSE CAMERA TO SPRAY ANTI-RUST PROOFING TO DIAGNSIS & REPROGRAMME SYSTEM LABOUR FOR PANEL BEATING TO PUTTY & SPRAY PAINTING

1 \$100.00 \ 17 \$100.00 X \$120.00 60 14 \$180.00 x \$1,800.00 6 80 \$1,800.00 900 \$18,869.90 TOTAL

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

TO PUTTY & SPRAY PAINTING TO CONDUCT WHEEL ALIGNMENT . 5150.00 P. N. A. RO