

ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | Cust No/Name KCV15418/Mr So Jeffrey Niu Reg No/Reg Date SMS3121K*# / 21/02/2020 Date In/Mileage 18/02/2022/ 17040 Chassis No GF7W0700331 Engine No 4J11CC3915 Make/Model MIT/20MY OUTLANDER 2.0 CVT STYLE (Colour/Trim U01 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | | |
|---------------------------------|--|-------------------|-----|----------------|--------|------------|---------|--------|-----------|
| F0000018 | Credit | 18/02/2022/ 16:42 | DS | 218 / Mars Ler | 26718 | | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount | |
| S | MIPNT88088 | | | | | | | | 250.00 |
| | DIAGNOSTIC / SCANNING | | | | | | | | 80 100.00 |
| S | MIPNT88088 | | | | | | | | |
| | TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS | | | | | | | | 640.00 |
| S | MIPNT88088 | | | | | | | | 280.00 |
| | TO REPLACE UNDERCARRIAGE DAMAGE PARTS | | | | | | | | 50.00 |
| S | MIPNT88088 | | | | | | | | |
| | TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT | | | | | | | | 800.00 |
| S | MIPNT88088 | | | | | | | | |
| | WHEEL BALANCING | | | | | | | | 2560.00 |
| S | MIPNT88088 | | | | | | | | |
| | TO REPLACE FRONT BODY KIT | | | | | | | | |
| S | MIPNT88088 | | | | | | | | |
| | TO REPLACE FRONT BUMPER,RHF FENDER PNL,ETC | | | | | | | | |
| | -TO REPAIR RHF FENDER APRON | | | | | | | | |
| | STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS | | | | | | | | 200.00 |
| S | MIPNT88088 | | | | | | | | |
| | TO APPLY SEALANT KIT ON NEW PANEL | | | | | | | | 2200.00 |
| S | MIPNT98088 | | | | | | | | |
| | SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS | | | | | | | | 863.00 |
| M | JJ6400K786 | | | | | 1.00 | 863.00 | 0.00 | 863.00 |
| | FACE,FR BUMPER | | | | | 1.00 | 1554.00 | 0.00 | 1554.00 |
| M | JJMZ576000A | | | | | 1.00 | 48.00 | 0.00 | 48.00 |
| | BODY KIT | | | | | 1.00 | 48.00 | 0.00 | 48.00 |
| M | JJ6407A142 | | | | | 6.00 | 5.00 | 0.00 | 30.00 |
| | GARNISH,FR BUMPER SI | | | | | 6.00 | 5.00 | 0.00 | 30.00 |
| M | JJMU001657 | | | | | 4.00 | 3.00 | 0.00 | 12.00 |
| | RIVET,FR BUMPER | | | | | 4.00 | 3.00 | 0.00 | 12.00 |
| M | JJMR590000HB | | | | | 10.00 | 2.00 | 0.00 | 20.00 |
| | CLIP | | | | | 10.00 | 2.00 | 0.00 | 20.00 |
| M | JJMU488006 | | | | | 20.00 | 3.00 | 0.00 | 60.00 |
| | CLIP | | | | | 20.00 | 3.00 | 0.00 | 60.00 |
| M | JJMR288150 | | | | | 1.00 | 18.00 | 0.00 | 18.00 |
| | CLIP | | | | | 1.00 | 18.00 | 0.00 | 18.00 |
| M | JJ6400H313 | | | | | 1.00 | 18.00 | 0.00 | 18.00 |
| | LH SIDE BRACKET,FR B | | | | | 1.00 | 18.00 | 0.00 | 18.00 |
| M | JJ6400H314 | | | | | 1.00 | 18.00 | 0.00 | 18.00 |
| | RH SIDE BRACKET,FR B | | | | | 1.00 | 18.00 | 0.00 | 18.00 |
| M | JJ8301D330 | | | | | 1.00 | 1948.00 | 0.00 | 1948.00 |
| | RH HEADLAMP ASSY | | | | | 1.00 | 1948.00 | 0.00 | 1948.00 |
| M | JJ5220K686 | | | | | 1.00 | 622.00 | 0.00 | 622.00 |
| | RH FR FENDER | | | | | 1.00 | 622.00 | 0.00 | 622.00 |
| M | JJ7407A674 | | | | | 1.00 | 97.00 | 0.00 | 97.00 |
| | RH MOULDING,FR BUMPE | | | | | 1.00 | 97.00 | 0.00 | 97.00 |

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | Cust No/Name KCV15418/Mr So Jeffrey Niu Reg No/Reg Date SMS3121K*# / 21/02/2020 Date In/Mileage 18/02/2022/ 17040 Chassis No GF7W0700331 Engine No 4J11CC3915 Make/Model MIT/20MY OUTLANDER 2.0 CVT STYLE (Colour/Trim U01 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No |
|------------|--------|-------------------|-----|----------------|--------|
| F0000018 | Credit | 18/02/2022/ 16:42 | DS | 218 / Mars Ler | 26718 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--|------|------------|-------|-----------------|
| M JJ7407A676 RH FR WHEEL ARCH MOU | 1.00 | 168.00 | 0.00 | Scr 168.00 |
| M JJ5370B882 RHF SPLASH SHIELD | 1.00 | 164.00 | 0.00 | Scr X 1. 164.00 |
| M JJ4060A660 RH FR SUSP STRUT | 1.00 | 410.00 | 0.00 | Scr X 1. 410.00 |
| M JJ4060A417 RH FR SUSP STRUT INS | 1.00 | 137.00 | 0.00 | Scr X 1. 137.00 |
| M JJ4250F623 WHEEL, DISC | 1.00 | 974.00 | 0.00 | Scr 974.00 |
| M WYK2255518-RV02 YOKOHAMA V552 225/55 | 1.00 | 250.00 | 0.00 | Scr X 250.00 |
| Z NOTES | | | | |

ACCIDENT ON 17/02/2022 ALONG TAMPINES STREET 41
OWNER CLAIMING THIRD PARTY
REQUIRED REPLACEMENT CAR
TP # SML4003Z TP INS : CHINA TAIPING

Thuan @ LK Auto. low
82235769
22/2/22 1030
P/p 5 days w/p

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

| | | |
|-----------------------|------------------------|------------------|
| Confirm & accepted by | Parts | 7,393.00 |
| | Labour | 0.00 |
| | Standard Menu | 0.00 |
| | Specialist Job | 7,080.00 |
| | Others (Lub, etc) | 0.00 |
| | Sundry | 0.00 |
| | Total (w/o GST) | 14,473.00 |

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | Cust No/Name KCV15418/Mr So Jeffrey Niu Reg No/Reg Date SMS3121K*# / 21/02/2020 Date In/Mileage 07/03/2022/ 17389 Chassis No GF7W0700331 Engine No 4J11CC3915 Make/Model MIT/20MY OUTLANDER 2.0 CVT STYLE (Colour/Trim U01 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | |
|---------------------------------|--------------------|---------------------|-----|----------------|-------------------------|--------|
| F0000018 | Credit | 11/03/2022/ 14:30 | DS | 218 / Mars Ler | 26718 | |
| Description of Goods / Services | | | | Qty | Unit Price Disc% Amount | |
| X | JJ7632A796 | RH DOOR MIRROR ASSY | | 1.00 | 558.00 0.00 | 558.00 |
| Z | NOTES | | | | | |
| | SUPPLEMENTARY ITEM | | | | | |
| Estimate | | | | | | |

Scr

Confirm & accepted by

Supplementary Item

Authorized signatory and company stamp

| | |
|-----------------|--------|
| Parts | 558.00 |
| Labour | 0.00 |
| Standard Menu | 0.00 |
| Specialist Job | 0.00 |
| Others(Lub,etc) | 0.00 |
| Sundry | 0.00 |
| Total(w/o GST) | 558.00 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

**ESTIMATE**

| Invoice Name & Address | Owner Name & Vehicle Info | |
|---|---------------------------|------------------------------------|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | Cust No/Name | KCV15418/Mr So Jeffrey Niu |
| | Reg No/Reg Date | SMS3121K*# / 21/02/2020 |
| | Date In/Mileage | 07/03/2022/ 17389 |
| | Chassis No | GF7W0700331 |
| | Engine No | 4J11CC3915 |
| | Make/Model | MIT/20MY OUTLANDER 2.0 CVT STYLE (|
| | Colour/Trim | U01 / BK |

| Account No | Terms | Date/Time Printed | CSE | Operator | WIP No | | | | |
|---------------------------------|--|----------------------|-----|----------------|--------|------------|-------|---------|---------|
| F0000018 | Credit | 11/03/2022/ 14:37 | DS | 218 / Mars Ler | 26718 | | | | |
| Description of Goods / Services | | | | | Qty | Unit Price | Disc% | Amount | |
| S | MIPNT88088 | | | | | | | | 250.00 |
| | DIAGNOSTIC / SCANNING | | | | | | | | |
| S | MIPNT88088 | | | | | | | | 80.00 |
| | TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS | | | | | | | | |
| S | MIPNT88088 | | | | | | | | 280.00 |
| | TO CONDUCT COMPUTERIZE WHEEL ALIGNMENT | | | | | | | | |
| S | MIPNT88088 | | | | | | | | 50.00 |
| | WHEEL BALANCING | | | | | | | | |
| S | MIPNT88088 | | | | | | | | 600.00 |
| | TO REPLACE FRONT BODY KIT | | | | | | | | |
| S | MIPNT88088 | | | | | | | | 1280.00 |
| | TO REPLACE FRONT BUMPER,RHF FENDER PNL,RH HEADLAMP ASSY,RH DOOR MIRROR ETC | | | | | | | | |
| | STRAIGHTEN,REFORM,ALIGN ON FRONT ACCIDENT AFFECTED AREAS | | | | | | | | |
| S | MIPNT88088 | | | | | | | | 100.00 |
| | TO APPLY SEALANT KIT ON NEW PANEL | | | | | | | | |
| S | MIPNT98088 | | | | | | | | 1100.00 |
| | SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS | | | | | | | | |
| X | JJ6400K786 | FACE,FR BUMPER | | | 1.00 | 863.00 | 0.00 | 863.00 | |
| M | JJMZ576000A | BODY KIT | | | 1.00 | 1554.00 | 0.00 | 1554.00 | |
| X | JJMU001623 | RIVET,FR BUMPER | | | 6.00 | 5.00 | 0.00 | 30.00 | |
| X | JJMR590000HB | CLIP | | | 4.00 | 3.00 | 0.00 | 12.00 | |
| X | JJMR328954 | CLIP | | | 10.00 | 2.00 | 0.00 | 20.00 | |
| X | JJMR288150 | CLIP | | | 20.00 | 3.00 | 0.00 | 60.00 | |
| X | JJ6400H314 | RH SIDE BRACKET,FR B | | | 1.00 | 18.00 | 0.00 | 18.00 | |
| X | JJ8301D330 | RH HEADLAMP ASSY | | | 1.00 | 1948.00 | 0.00 | 1948.00 | |
| X | JJ5220K686 | RH FR FENDER | | | 1.00 | 622.00 | 0.00 | 622.00 | |
| X | JJ7407A674 | RH MOULDING,FR BUMPE | | | 1.00 | 97.00 | 0.00 | 97.00 | |
| X | JJ7407A676 | RH FR WHEEL ARCH MOU | | | 1.00 | 168.00 | 0.00 | 168.00 | |
| M | JJ4250F623 | WHEEL,DISC | | | 1.00 | 974.00 | 0.00 | 974.00 | |
| X | JJ7632A796 | RH DOOR MIRROR ASSY | | | 1.00 | 558.00 | 0.00 | 558.00 | |
| Z | NOTES | | | | | | | | |

Confirm & accepted by

Finalization

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE·FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

| Invoice Name & Address | Owner Name & Vehicle Info |
|---|--|
| CHINA TAIPING INSURANCE (SINGAPORE) 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Claims Dept. Contact No 63896111 | Cust No/Name KCV15418/Mr So Jeffrey Niu Reg No/Reg Date SMS3121K*# / 21/02/2020 Date In/Mileage 07/03/2022/ 17389 Chassis No GF7W0700331 Engine No 4J11CC3915 Make/Model MIT/20MY OUTLANDER 2.0 CVT STYLE (Colour/Trim U01 / BK |

| Account No | Terms | Date/Time Printed | GSE | Operator | WIP No |
|------------|--------|-------------------|-----|----------------|--------|
| F0000018 | Credit | 11/03/2022/ 14:37 | DS | 218 / Mars Ler | 26718 |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|--|-----|------------|-------|--------|
| ACCIDENT ON 17/02/2022 ALONG TAMPINES STREET 41 OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR (CHAN'S) TP # SML4003Z TP INS : CHINA TAIPING | | | | |

Estimate

Confirm & accepted by

Finalization

Authorized signatory and company stamp

| | |
|-----------------|-----------|
| Parts | 6,924.00 |
| Labour | 0.00 |
| Standard Menu | 0.00 |
| Specialist Job | 3,740.00 |
| Others(Lub,etc) | 0.00 |
| Sundry | 0.00 |
| Total(w/o GST) | 10,664.00 |

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.