

Our Job Ref No : 305504001  
Date : 11/02/22

## COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508989  
Fax: 6546 8156

### FINALIZATION FORM

To : LKK  
Attn : THEVAN  
Vehicle Reg No. : SHA7729K

Fax :

Date of Accident : 30.01.22

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-


1. The repair job shall bill to: NTUC --- SJQ8849H
2. The finalized amount shall be:
  - (a) Spare Parts after List discount
  - (b) Labour Charges (include advertisement stickers etc, if any)  
**Total for Part-By-Part Repair Cost**  
~~630~~  
~~630~~
  - (c) Lumpsum Repair (if applicable)  
Total for Lumpsum repair cost after Less: 20%  
**Final Lumpsum Repair cost**  
~~500.00~~  
~~500.00~~


3. Estimated normal period for repairs: 2 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :   
Name : LIM T S  
Tel : 62148398  
Fax : 65468156

Signature :   
Name : THEVAN  
Date :

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

\_\_\_\_\_

## COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

## REPAIR ESTIMATE

DATE: 7-Feb-22MODEL: Hyundai IoniqVEHICLE NO.: SHA7729KINSURANCE: NTUC (LKS)MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Bumper	1		\$459.40 X
	Rear Bumper Centre Moulding Assy	1		\$451.25 X SUC
	Rear Bumper Lower Moulding Assy	1		\$155.00 X SUC
	Rear Bumper Cover Clips	10	\$2.20	\$22.00 X SUC
	Rear Bumper FogLamp	1		\$201.50 X SUC
	<b>SUB TOTAL</b>			\$1,289.15
	<b>LESS 20%</b>			\$257.83
	<b>DISCOUNTED TOTAL</b>			\$1,031.32
	Rear No. Plate With Trim Cover	1		\$55.00 X SUC
	Rear Bumper Reverse Sensor	1		\$180.00 X SUC
	<b>S/NETT SUB</b>			\$235.00
	<b>LESS 10%</b>			\$23.50
	<b>S/NETT TOTAL</b>			\$211.50
	Rear Bumper Mat			\$50.00
	<b>SPARE PARTS TOTAL</b>			\$1,292.82
	<u>Labour Charge</u>			
	Panel Beating			\$400.00
	Spray Painting Charge			\$300.00
	Remove/Refix Reverse Sensor			\$120.00
	<b>TOTAL LABOUR</b>			\$820.00
	<b>ESTIMATE TOTAL</b>			\$2,112.82

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thuan 82235769  
 7/2/22 1715  
 Labour only no - 20/6  
 2 days up

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: