

Our Job Ref No : 305504062

Date : 12/02/22

**COMFORTDELGRO
ENGINEERING**

ComfortDelGro Engineering Pte Ltd
591 Upper Drive Singapore 548499
Fax 6548 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : THEVAN

Vehicle Reg No. : SHD3229Y

28.01.2022

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

2. The repair job shall bill to: NTUC SLL3642Y
2. The finalized amount shall be:
- (a) Spare Parts after List discount
- (b) Labour Charges
- Total for Part-By-Part Repair Cost**
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: \$1,500.00
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days.

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.


We confirm the estimates and finalized amount

Signature : 

Name : CHIANG

Tel : 62148314

Fax : 65468156

Signature : 

Name :

Date :

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	-	N		
3. Survey Fees	-	-		
4. LTA Search Fee	\$7.49/\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

REPAIR ESTIMATE*

VEHICLE NO SHD3229Y

DATE 29/01/2022

MAKE REG 12.05.2016

CHIANG /NTUC

MODEL HYU- I40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				\$663.00
1	FENDER LH			\$174.90
1	FENDER SHIELD LH			\$14.30
1	FRONT BUMPER SIDE RH /LH			\$2,256.40
1	FRONT DOOR LH			\$670.00
1	FRONT DOOR WING LH			\$214.20
1	WHEEL HUB COVER			\$3,992.80
	SUB TOTAL			\$798.56
	20.00%			\$3,194.24
	DISCOUNTED TOTAL			\$75.00
1	FRT DOOR LOGO STICKER			\$75.00
	Labour Charge			\$560.00
	Panel Beating			\$600.00
	Spray Painting Charge			\$60.00
	Check wiring			\$60.00
	Tuff kote			\$1,220.00
	TOTAL LABOUR			
	ESTIMATE TOTAL			\$4,489.24
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

2

Thevan 82235769

7/2/22 1730

L/S after repair photo

2 days 3 days wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: