ĩ

D	
_	
Q€	

ΞD		
_		
교		
lg€		
3 N		
ne		

Our Job Ref No : 305504340 Date : 11/02/22		COMFORTDELGRO ENGINEERING ComfortDelGro Engineering Pte Ltd					
FINALIZ	ATION FORM			59 Loyang Dr Fax: 6546 81	lve Singapore 508969 56		
To :	L	KK	_	Fax:			
Attn :	Th	IEVAN					
Vehicle F	Reg No. : SHD32	216J	Date	of Accident :	07/02/22		
The surv	ey and estimates of th	e repairs of the abov	e-mentioned ve	hicle are as follo	ows:-		
1. Th	ne repair job shall bill to	o:	NTUC	***	SLZ9924X		
2. Th	ne finalized amount sh	all be:					
(a) Spare Parts after	List discount					
(b)) Labour Charges	(include advertisem	ent stickers etc,	if any)			
	Total for Part-By	-Part Repair Cost					
(c.		n repair cost after Le	ess: 20%		\$950.00 \$950.00		
4. We	timated normal period e shall treat the abov thin 7 working days	re amount as Corre	ct and Confirn				
5. Th	5. Thank you for your assistance.			We confirm the estimates and finalized amount			
Signature: LIM T S			Signature : THEVAN				
Tel			Da	te :	x 40 000 0 0 0 0		
Fax	: <u>65468156</u>	5					
For Offici	al Use Only						
	ltem	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks		
1. Rental	Rate P/Day		YES	to all to make the a			
2. Loss o	f Income Paid		N		,		
3. Survey	Fees						
	earch Fee	\$7.49 /\$2.00					
 Medica driver. 	I Fees (on behalf of if applicable)		l				
Overru							
Remarks:			;				

am

IMC

IMC SS (F)

TI N(01 **REPAIR ESTIMATE**

8-Feb-22

MODEL:

Hyundai i40

VEHICLE NO .: SHD3216J

DATE:

INSURANCE: NTUC CHS)

MVA: LIMTS

DESCRIPTION	QTY	UNIT PRICE	AMOUNT
			OT
Rear Bumper	1		\$553.00
Rear Bumper Under Cover	1		\$228.00 X Suc
Rear Bumper Sponge	1		\$119.50
Rear Bumper Reinforcement	1		\$420.40
			ψ100.00
Rear Bumper Clips	10	\$2.20	\$22.00
SUB TOTAL			\$1,511.50
500 Section 10 Section		1	\$302.30
DISCOUNTED TOTAL			\$1,209.20
			\$50.00
Rear Bumper Mat	1		\$30.00
Reverse Sensors	1	1	\$135.70
NETT TOTAL			\$185.70
SPARE PARTS TOTAL			\$1,394.90
Labour Charge			\$300.00 2
	1		\$300.00 2
1 - 100			\$120.00
R/I Reverse Sensors			ψ120.00
TOTAL LABOUF	2		\$720.00
			\$2,114.90
	Rear Bumper Rear Bumper Under Cover Rear Bumper Sponge Rear Bumper Reinforcement Rear Bumper Reinforcement Bracket RH / LH Rear Bumper Clips SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Mat Reverse Sensors NETT TOTAL SPARE PARTS TOTAL Labour Charge Panel Beating Spray Painting Charge R/I Reverse Sensors	Rear Bumper Rear Bumper Under Cover Rear Bumper Sponge Rear Bumper Reinforcement Rear Bumper Reinforcement Bracket RH / LH Rear Bumper Clips SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Mat Reverse Sensors 1 NETT TOTAL SPARE PARTS TOTAL Labour Charge Panel Beating Spray Painting Charge	Rear Bumper Under Cover Rear Bumper Sponge Rear Bumper Reinforcement Rear Bumper Reinforcement Rear Bumper Reinforcement Bracket RH / LH Rear Bumper Clips SUB TOTAL LESS 20% DISCOUNTED TOTAL Rear Bumper Mat Reverse Sensors 1 NETT TOTAL SPARE PARTS TOTAL Labour Charge Panel Beating Spray Painting Charge R/I Reverse Sensors

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Theran \$2235769 8/16/22 1630 L(S after repair photo 2days wp

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: