


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: *SMH 2264X*
 at Workshop m/s *Zankim*
 of _____
 Insured: *SMJ 6957T*
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: *\$80k.*
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: *4* days Res.: Yes or No
 Lump Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: *Dep 10K.*

Veh No: *SMH 2264X* Yr Regn: *16/11/19*
 Type: *M/Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or *CA*
 Make: *Toyota C-HR Hybrid* 1797
 Colour: *white* A/C: Insured / Std / NI / NA
 Sp. Reading: *244597* T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: *21X1021 42880*
 Gen. Cond: *Good* / Fair / Poor / Burnt
 Steering: *Inorder* / Jammed / Leaked / Burnt or
 Brake: *Inorder* / Jammed / Leaked / Burnt or
 Modi: *Nil* / S/Rim / STD A/Rim or
 Tyre Size: F: *215/60 R17*
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / *MIC* / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front *6* Rear *6*
 R/Bal. *6* mm R/Bal. *6* mm
 L/Bal. *6* mm L/Bal. *6* mm
 D.O.A. *19/2/22* D.O.I. *22/2/22*
 Survey held at _____

Des. of Damages : Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

27A 37887

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$) ☐ S + RS ☐ SI
☐ Interview (\$) Photos
☐ Tech. Invs (\$) Others
☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I.: (\$)

TOTAL

26/2/22 1/5 @ 5300 internet million



Lonpac Msia Insured's Veh No : SMJ6957T

Date of Accident : 19 February 2022

TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Boyd Chng Services

Date : 21 February 2022

Estimate To Repair SMH2264X - Toyota C-HR Hybrid 1.8S CVT

Chassis No : ZYX102142880

S/No	Quantity	Description	Amount
		LIST ITEMS	
01	1 pc	front bumper	\$ 597.60
02	8 ps	front bumper clips @ \$5.00	\$ 40.00
03	1 pc	front bumper lower	\$ 222.80
04	1 pc	front bumper centre grille	\$ 100.50
05	1 pc	front bumper side retainer o/s	\$ 115.10
06	1 pc	o/s headlamp	\$ 4,396.80
07	1 pc	o/s front fender	\$ 826.00
08	1 pc	o/s front fender inner cowl	\$ 236.70
09	8 ps	o/s front fender inner cowl clips @ \$5.00	\$ 40.00
10	1 pc	o/s front fender outer garnish	\$ 143.60
11	1 pc	front bumper beam	\$ 276.80
12	1 pc	front bumper foam	\$ 70.30
13	1 pc	wiper tank	\$ 258.60
14	1 pc	wiper tank motor	\$ 339.70
15	2 ps	front bumper sensor @ \$223.70	\$ 447.40
		Less 25 %	\$ 8,111.90
			\$ 2,027.98
			\$ 6,083.93
		SPECIAL NETT ITEMS	
16	1 pc	front licence plate	\$ 50.00
			\$ 50.00
		LABOUR & MISC. CHARGES	
01		To check electrical lighting concerned.	\$ 60.00
02		To reinstall of front bumper parking sensor.	\$ 80.00
03		To rust-proofing of the affected areas.	\$ 80.00
04		Panel beating, knocking and straighten the necessary portion,	\$ 650.00
05		remove and renewal of parts, adjust and realign the same.	\$ 750.00
		Putty and spray painting of the affected portion.	\$ 1,620.00
		Total	\$ 7,753.93
			7408.20
			257
			7665.15



陳林摩時私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Lonpac Msia Insured's Veh No : SMJ6957T

Date of Accident : 19 February 2022

Messrs Boyd Chng Services

Date : 22 February 2022

Supplementary To Repair SMH2264X - Toyota C-HR Hybrid 1.8S CVT

Chassis No : ZYX102142880

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	front bumper under cover <i>Torn</i>	\$ 130.00
02	1 pc	front bumper lower sponge <i>Torn</i>	\$ 178.00
03	1 pc	o/s fog lamp assembly <i>Che</i>	\$ 410.00
			<i>350</i>
Less 25 %			\$ 718.00
			\$ 179.50
Total			\$ 538.50
			\$ 538.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: