

REPAIR ESTIMATE\*

VEHICLE NO SHD3587M

17/2/22

MAKE

MODEL HYU- I40

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER		553	<del>\$1,106.00</del>
2	REAR BUMPER BRACKET SIDE LH /RH		<del>Prx</del> <sup>nm</sup> \$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR WHEEL COVER LH			\$216.00
1	REAR WHEEL RIM LH			\$650.60
1	REAR LOWER ARM LH			\$335.75
1	REAR UPPER ARM LH			\$353.80
1	REAR KNUCKLE LH			\$545.60
1	REAR ASSIST ARM LH			\$291.00
		826.60	<del>1377.80</del>	\$3,819.95
		661.28		\$763.99
	20.00% DISCOUNTED TOTAL		<del>1100.30</del>	\$3,055.96
1	REAR BUMPER MAT			\$50.00
1	TYRE REAR LH		172.80 80%	\$216.00
1	REVERSE SENSOR		222.80	\$135.70
				\$366.53
	<b>Labour Charge</b>			
	Panel Beating			\$700.00
	Spray Painting Charge			\$500.00
	Remove and Refix under carriage			<del>nm</del> X \$120.00
	Check lighting		870.	\$50.00
	Reset wheel alignment			\$60.00
	Remove/refix reverse sensor	1754.08	<del>219.60</del>	\$60.00
	Tuff Kote	1/s\$1400	<del>1100</del>	\$60.00
	<b>TOTAL LABOUR</b>	2 days	<del>219.60</del>	\$1,550.00
	<b>ESTIMATE TOTAL</b>		<del>219.60</del>	\$4,972.49
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97415749  
 'MP' 18/2/22 @ 4pm  
 1/3 Resurvey after repair  
 2 days  
 Tanpin @ LKK Auto Consultants