

ASS. REG. BY: Taufik

REF:

NS/INC22001664/Tqy3
INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. MT/1162990-002

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WRDate: _____ Person Contacted: Amir

Vehicle: IN / OUT

Veh No: SHD3587M Yr Regn: 24.6, Sep.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 140 c.c. 1685Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 682887 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCB414MG 4093708Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60R16R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. _____ D.O.I. 18/2/22Survey held at Comfort Lodge

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

n/s rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Taufikh finalised LS \$1400, 2 days (Red \$3572.49, 72%)

Date/Time, File Pass to?

☐ : Preli. Report1) 22/03 Typist☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 2Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: TPLump Sum / LS / \$ 1400

COMFORTDELGRO ENGINEERING PTE LTD.

REPAIR ESTIMATE*

VEHICLE NO SHD3587M

17/2/22

MAKE

MODEL HYU- I40

CHIANG /NTUC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH /RH		PRX \$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR WHEEL COVER LH			\$216.00
1	REAR WHEEL RIM LH			\$650.60
1	REAR LOWER ARM LH			\$335.75
1	REAR UPPER ARM LH			\$353.80
1	REAR KNUCKLE LH			\$545.60
1	REAR ASSIST ARM LH			\$291.00
				\$3,819.95
	20.00% DISCOUNTED TOTAL			\$763.99
				\$3,055.96
1	REAR BUMPER MAT			\$50.00
1	TYRE REAR LH			\$216.00
1	REVERSE SENSOR			\$135.70
				\$366.53
	Labour Charge			
	Panel Beating			\$700.00
	Spray Painting Charge			\$500.00
	Remove and Refix under carriage			\$120.00
	Check lighting			\$50.00
	Reset wheel alignment			\$60.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
	TOTAL LABOUR			\$1,550.00
	ESTIMATE TOTAL			\$4,972.49
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97415749
 'MP' 15/2/22 @ 4pm
 1/3 Resurvey after repair
 2 days
 Tanpin @ LKK Auto Consultants

Workshops

205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508989
383 Sin Ming Drive Singapore 575717

Date/Time: 18.02.2022 15:28

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4175350

JC NO 305505443

CUSTOMER

CUSTOMER NAME: COMFORT TRANSPORTATION PTE LTD

CUSTOMER NO. 7010045

ADDRESS: 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(P)

(O)

COUNT CARD NO.

REGN NO.:

SHD3587M

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN
17.02.2022 14:00

YR OF MANU.

08.09.2016

TARGET DATE

CHASSIS CODE

KMHLB41UMGU093708

COMPLETION DATE/TIME:

Accident Date: 17.02.2022


NATURE: 3P 17.02.2022

JOB DESCRIPTION

/NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

to: SHD3587M

CHIANG

Vehicle No.:

SHD3587M

Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard