

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: jlpperfectautowok@gmail.com



HD PERFECT
AUTOWORK PTE LTD

Cecilia.

DATE : 17.02.2022

GK33427543

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMP7534S**
MODEL : **HONDA FIT**
DATE OF ACCIDENT : 16.02.2022
TIME OF ACCIDENT : 16:30HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 710.30	\$ <u>710.30</u> <i>495</i>
2	REAR BUMPER EXHAUST GARNISH <i>new</i>	1	\$ 29.10	\$ 29.10 <i>+</i>
3	REAR BUMPER SIDE COVER GARNISH <i>Dehd</i>	2	\$ 49.60	\$ 99.20 <i>-</i>
4	REAR BUMPER CENTER GARNISH <i>Dehd</i>	1	\$ 192.10	\$ 192.10 <i>✓</i>
5	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 35.20	\$ 70.40 <i>-</i>
6	TAIL GATE <i>Dehd</i>	1	\$ 860.60	\$ 860.60 <i>✓</i>
7	TAIL GATE LAMP <i>Rd int</i>	2	\$ 193.20	\$ 386.40 <i>193.20</i>
8	TAIL GATE OUTER MOULDING <i>new</i>	1	\$ 197.80	\$ 197.80 <i>+</i>
9	TAIL GATE LOGO <i>new</i>	1	\$ 37.10	\$ 37.10 <i>+</i>
10	TAIL GATE EMBLEM 'FIT' <i>new</i>	1	\$ 47.20	\$ 47.20 <i>✓</i>
11	TAIL GATE DAMPER <i>new</i>	2	\$ 104.20	\$ 208.40 <i>+</i>
12	TAIL GATE INNER HOLDER <i>new</i>	1	\$ 47.10	\$ 47.10 <i>+</i>
13	TAIL GATE STOPPER <i>Not Nec</i>	2	\$ 12.00	\$ 24.00 <i>+</i>
14	TAIL GATE INNER LOCK <i>Damaged</i>	1	\$ 157.10	\$ 157.10 <i>✓</i>
15	TAIL GATE LOCK CATCH <i>Not new</i>	1	\$ 25.00	\$ 25.00 <i>+</i>
16	TAIL GATE WEATHER STRIP <i>int</i>	1	\$ 167.50	\$ 167.50 <i>✓</i>
17	TAIL GATE INNER TRIM <i>Conhd</i>	1	\$ 199.60	\$ 199.60 <i>✓</i>
18	TAIL GATE HINGE <i>Not new</i>	2	\$ 65.80	\$ 131.60 <i>+</i>
19	TAIL GATE DETECTOR <i>Conhd</i>	1	\$ 267.30	\$ <u>267.30</u> <i>145</i>
20	TAIL GATE BUZZER <i>Dmgd</i>	1	\$ 126.10	\$ 126.10 <i>-</i>
21	TAIL GATE WINDSCREEN MOULDING <i>new</i>	2	\$ 95.00	\$ 190.00 <i>-</i>
22	TAIL LAMP <i>CH int</i>	2	\$ 297.40	\$ 594.80 <i>297.40</i>
23	REAR FENDER INNER COWLING <i>new</i>	2	\$ 97.10	\$ 194.20 <i>+</i>
24	REAR FENDER INNER TRIM <i>LA torn</i>	2	\$ 298.90	\$ 597.80 <i>298.90</i>
25	REAR END PANEL <i>Dented</i>	1	\$ 394.10	\$ 394.10 <i>✓</i>
26	REAR END PANEL TOP GARNISH <i>Dehd</i>	1	\$ 164.30	\$ 164.30 <i>✓</i>

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SMP7534S
 MODEL : HONDA FIT
 DATE OF ACCIDENT : 16.02.2022
 TIME OF ACCIDENT : 16:30HRS

27	REAR TOWING HOOK PANEL <i>Repair</i>	1	\$ 297.30	\$ 297.30	+
28	REAR FLOOR PANEL <i>Repair</i>	1	\$ 796.10	\$ 796.10	+
29	REAR FLOOR PANEL TOP BOARD <i>Delint</i>	1	\$ 198.60	\$ 198.60	✓
30	REAR TOOLS COMPARTMENT SPONGE <i>do.in</i>	1	\$ 212.30	\$ 212.30	✓
31	REAR CHASSIS FRAME RH <i>Repair</i>	1	\$ 849.20	\$ 849.20	✓
32	REAR CHASSIS TOP PANEL RH <i>Repair</i>	1	\$ 295.50	\$ 295.50	+
33	REAR EXHAUST PIPE <i>Repair</i>	1	\$ 673.70	\$ 673.70	+
34	REAR EXHAUST INSULATOR	1	\$ 58.40	\$ 58.40	+
35	REAR EXHAUST GASKET (SET)	1	\$ 60.00	\$ 60.00	+
36	REAR EXHAUST MOUNTING	4	\$ 21.20	\$ 84.80	+
			4508.60		
			3606.88		
			TOTAL PRICE	\$ 9,645.00	
			LESS 20%	\$ 1,929.00	
			SUB TOTAL PRICE	\$ 7,716.00	

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE <i>Not Rec</i>	1	\$ 80.00	\$ 80.00	+
2	REAR BUMPER CLIP (SET) <i>Rec</i>	1	\$ 80.00	\$ 80.00	30
3	REAR BUMPER CENTER GARNISH CLIP (SET) <i>Not Rec</i>	1	\$ 60.00	\$ 60.00	+
4	TAIL GATE INNER TRIM CLIP (SET) <i>Rec</i>	1	\$ 60.00	\$ 60.00	30
5	TAIL GATE WINDSCREEN SEALANT <i>2pc</i>	1	\$ 80.00	\$ 80.00	30
6	TAIL GATE WINDSCREEN INNER SEAL	1	\$ 60.00	\$ 60.00	40
7	TAIL GATE WINDSCREEN SOLAR FILM <i>Rec</i>	1	\$ 500.00	\$ 500.00	+
8	TAIL LAMP CLIP (SET) <i>Rec</i>	1	\$ 50.00	\$ 50.00	20
9	REAR FENDER INNER COWLING CLIP (SET) <i>Not Rec</i>	1	\$ 80.00	\$ 80.00	+
10	REAR FENDER INNER TRIM CLIPS (SET) <i>Rec</i>	1	\$ 80.00	\$ 80.00	30
11	REAR END PANEL INSULATION SEAL <i>Rec</i>	1	\$ 150.00	\$ 150.00	60
12	REAR TOWING HOOK PANEL SEALANT <i>Not Rec</i>	1	\$ 80.00	\$ 80.00	+
13	REAR FLOOR PANEL SEALANT <i>Not Rec</i>	1	\$ 350.00	\$ 350.00	+
14	REAR CHASSIS MEMBER TOP PANEL SEALANT RH <i>Not Rec</i>	1	\$ 120.00	\$ 120.00	+
15	REVERSE CAMERA <i>Not Rec</i>	1	\$ 450.00	\$ 450.00	+
16	REVERSE SENSOR (2PCS) (SET) <i>Damaged</i>	1	\$ 220.00	\$ 220.00	20
			440		
			TOTAL	\$ 2,500.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00	80
3	TUFF COAT	\$ 250.00	60

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SMP7534S**
 MODEL : **HONDA FIT**
 DATE OF ACCIDENT : 16.02.2022
 TIME OF ACCIDENT : 16:30HRS

4	WIRING CHECK	\$ 180.00	30
5	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
6	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50
8	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	50
9	REMOVE AND VIDEO FOOTAGE AND DISTANCE SETTING	\$ 80.00	50
10	REAR CHASSIS ALIGNMENT	\$ 250.00	X.
11	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
12	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
13	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	150.
14	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 280.00	X

2450

TOTAL \$ 5,610.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 10,216.00
 TOTAL LABOUR COST : \$ 5,610.00
 TOTAL REPAIR COST : \$ 15,826.00

Adrian King
 L/S 18/02/22.
 06 Days-

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Total: 3496.88

L/S: 52K

5.2K