

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI22001671/KVY3E2

Date: 29/07/2022

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00155002100
Claimant Vehicle No : SNA6639Y Insured Vehicle No : XE6860J
Date of Loss: 21/01/2022 Nature of Claim: TP Claim No: SNM22D200603/C02/TANCHC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNA6639Y**
Make & Model: BMW 216I, 1.5 ACTIVE TOURER (A) Engine No: 42376345B38A15A
Reg. Date: 01/07/2021 (Man. Year: 2021) Chassis No: WBA2X920X07H96740
Colour: Metallic Black Odometer: 10353 km
Engine Capacity: 1499 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R17 Rear Tyre Size: 205/55 R17
Front Left Side: Bridgestone 9 mm Rear Left Side: Bridgestone 9 mm
Front Right Side: Bridgestone 9 mm Rear Right Side: Bridgestone 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	860.00	580.00	280.00	32.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	860.00	580.00	280.00	32.56
+ GST 7.00/7.00% (S\$)	60.20	40.60	19.60	32.56
Nett Amount (S\$)	920.20	620.60	299.60	32.56

INSPECTION

Date of Assignment: 21/02/2022 Present Location: Cheng Hoe Motor Pte Ltd (Yishun)
Date Inspected: 24/02/2022 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair: 2.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2022)
Parts:	143	BMW 216I 1.5 ACTIVE TOURER (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNA6639Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIX REAR BUMPER ASSY,REVERSE SENSORS,TO REPAIR AND REALIGN REAR BUMPER AND RESET REVERSE SENSOR	New	360.00	180.00
2	PUTTY & RESPRAY ON REAR BUMPER,REAR BUMPER CENTRE PROTECTOR AND REAR LH FENDER	New	500.00	400.00
Gross Labour Cost (\$\$)			860.00	580.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >