



進友成汽車服務有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

MR MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
ATTN: MOTOR CLAIMS DEPT

POLICY NO : D-21097398MVPC
OUR REF : OD 3528
VECHICLE NO : SFP 6883 Z
MAKE/MODEL : TOYOTA COROLLA ALTIS
CHASSIS : MR053REH104508248
DATE OF ACCIDENT : 18.02.22

SURVEY BY

DATE : 19.02.22

1	PC	BONNET		S\$	1,248.82
2	PCS	BONNET HINGES	56.90		113.80
1	PC	BONNET WEATHERSTRIP			47.30
1	PC	BONNET LOCK			178.10
1	PC	BONNET INSULATOR			280.10
1	PC	BONNET STAND STOPPER			13.70
1	PC	FRONT GRILLE			643.10
1	PC	FRONT GRILLE EMBLEM			25.60
2	PCS	HEADLAMP ASSY	2,999.80		5,999.60
1	PC	FRONT BUMPER			531.10
2	PCS	FRONT BUMPER SIDE RETAINERS	85.50		171.00
1	PC	FRONT BUMPER LOWER GRILLE			170.10
1	PC	FRONT BUMPER REINFORCEMENT			399.50
1	PC	FRONT BUMPER SPONGE			90.10
2	PCS	FRONT BUMPER BRACKETS	78.30		156.60
1	PC	FRONT SUPPORT PANEL			1,136.30
1	PC	FRONT SUPPORT PANEL TOP GARNISH			80.70
1	PC	FRONT BRACE PANEL			149.40
2	PCS	HORN	120.70		241.40
1	PC	AIR-CON CONDENSER			1,801.70
1	PC	AIR-CON SUCTION PIPE			531.40
2	PCS	AIR-CON LOWER MOUNTING	37.80		75.60
1	PC	RADIATOR			2,148.90
1	PC	RADIATOR FAN MOTOR			535.50
1	PC	RADIATOR FAN BLADE			180.40
1	PC	RADIATOR FAN COWLING			297.20
2	PCS	RADIATOR TOP BRACKET	59.70		119.40
1	PC	RADIATOR BY PASS HOSE			51.78
1	PC	RADIATOR TOP HOSE			78.90
1	PC	RADIATOR SPARE TANK			190.10
1	PC	RADIATOR TOP GARNISH			101.00
2	PCS	RADIATOR LOWER BUSH	23.70		47.40
1	PC	WASHER TANK			219.10
1	PC	AIR CLEANER BOX			1,140.10
1	PC	RESONATOR BOX			107.00
1	PC	RESONATOR BAX AIR VENT			191.05
2	PCS	IMPACT SENSOR	250.00		500.00
1	SET	BATTERY BRACKET			36.40
2	PCS	FRONT FENDER	908.70		1,817.40
2	PCS	FRONT FENDER INNER SHIELD	209.10		418.20
2	PCS	FRONT FENDER "VVTI" EMBLEM	44.17		88.34
2	PCS	FRONT FENDER INNER PANEL	440.80		881.60
				S\$	23,234.79
LESS 25%					5,808.70
				S\$	17,426.09



進友成汽車服務有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

CON'T FROM PAGE-1

		S\$	17,426.09	
1 PC	FRONT WINDSCREEN GLASS	S\$	1,743.60	
1 PC	FRONT WINDSCREEN GLASS MOULDING		76.00	
1 PC	DASHBOARD		2,265.00	
1 PC	DASHBOARD AIR-BAG		3,869.30	
1 PC	STEERING WHEEL AIR-BAG		2,867.40	
1 PC	STEERING WHEEL AIR-BAG CONTACT PIERE		545.90	
2 PCS	SAFETY BELT	995.10	1,990.20	
		S\$	13,357.40	
	LESS 25%		3,339.35	
		S\$	10,018.05	
10 PCS	BONNET INSULATOR CLIPS	S\$	35.00	S/ NETT
5 PCS	FRONT GRILLE CLIPS		20.00	"
10 PCS	FRONT BUMPER CLIPS		28.00	"
1 PC	FRONT NUMBER PLATE		45.00	"
5 PCS	FRONT SUPPORT PANEL TOP GARNISH CLIPS		18.00	"
1 PC	BATTERY		120.00	"
20 PCS	FRONT FENDER INNER SHIELD CLIPS		60.00	"
1 PC	FRONT WINDSCREEN GLASS SEALANT		40.00	"
1 PC	ERP BRACKET		26.00	"
		S\$	392.00	
TO TOWING CHARGES		S\$	100.00	
TO REMOVE AND RENEW FRONT WINDSCREEN GLASS			140.00	
TO REMOVE AND REFIX DASHBOARD & RELATED WIRE HARDNESS			350.00	
TO REMOVE AND REPLACE AIR-BAG SYSTEM			250.00	
TO RE-SET AIR-BAG SYSTEM			250.00	
TO REMOVE AIR-CON CONDENDER,PIPE,DRIER AND TOP-UP AIR-CON GAS			120.00	
TO CHECK WIRING FUNCTION			60.00	
LABOUR CHARGES			1,300.00	
TO PUTTY AND SPRAY PAINTING CHARGES			1,500.00	
		<u>S\$</u>	<u>31,906.14</u>	

SIN DOLLARS. THIRTY-ONE THOUSAND NINE HUNDRED SIX AND CENTS FOURTEEN ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD