



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                       |   |   |                            |                |
|---|---|---|----------------------------|----------------|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877 |   |   | Ref: CS/FCI22001676/Rtf3e2 |                |
|   |   |   | Date: 10/03/2022           |                |
|   |   |   | Code: FCI2                 |                |
| <b>1. Policy Particulars :- OWN DAMAGE</b>  |   |   |                            |                |
|   | <b>Insured Veh.</b>   |   | <b>Veh. Inspected</b>      | SFP 6883Z      |
|   | <b>Policy No.</b>   | D-21097398MVPC  | <b>Coverage (\$)</b>       | 0.00           |
|   | <b>Claim No.</b>  | D22000485MVPC   | <b>Excess (\$)</b>         | 500.00         |
|   | <b>Assign From</b>  | CHRIS LIM   | <b>Assign Date</b>         | 22/02/2022     |
| <b>2. Vehicle Particulars &amp; Condition</b>   |   |   |                            |                |
|   | <b>Make &amp; Model</b>   | TOYOTA COROLLA ALTIS 1.6L   | <b>c.c</b>                 | 1598           |
|   | <b>Engine No.</b>   | HIDDEN  | <b>Year of Reg.</b>        | 2014           |
|   | <b>Chassis No.</b>  | MR053REH104508248   | <b>Colour</b>              | GREY           |
|   | <b>Odometer</b>   | 252458 KM   | <b>Steering</b>            | IN ORDER       |
|   | <b>Brakes</b>   | IN ORDER  | <b>Modification</b>        | SPORTS RIM     |
|   | <b>General</b>  | FAIR  |                            |                |
| <b>3. Conditions of Tyres</b>   |   |   |                            |                |
|   |   | <b>Size</b>   | <b>Make</b>                | <b>Balance</b> |
|   | <b>R/H Front Tyre</b>   | 205/55 R16  | MICHELIN                   | 6 mm           |
|   | <b>L/H Front Tyre</b>   | 205/55 R16  | MICHELIN                   | 6 mm           |
|   | <b>R/H Rear Tyre</b>  | 205/55 R16  | MICHELIN                   | 6 mm           |
|   | <b>L/H Rear Tyre</b>  | 205/55 R16  | MICHELIN                   | 6 mm           |
| <b>4. Description of Damages</b>  |   |   |                            |                |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.<br><br>DAMAGES SEE DETAILS.   |   |                            |                |
| <b>5. General Information</b>   |   |   |                            |                |
|   | <b>Accident Date</b>  | 18/02/2022  | <b>Inspection Date</b>     | 22/02/2022     |
|   | <b>Survey held at</b>   | CYS AUTOMOBILE SERVICES PTE LTD<br>38 WOODLANDS INDUSTRIAL PARK EAST 1<br>#07-17<br>ADMIRALTY INDUSTRIAL PARK<br>SINGAPORE 757700 |                            |                |
| <b>5a. Remarks</b>  |   |   |                            |                |
|   | A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE MARKET VALUE IS S\$35,000.00 (EST. AVERAGE)<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. |   |                            |                |
| <b>5b. Estimate Days of Repair</b>  |   |   |                            |                |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:   |   | <b>10 Working Days</b>     |                |