



進友成汽車服務有限公司

CYS Automobile Services Pte Ltd

ROC Reg. No : A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

MR MS FIRST CAPITAL INSURANCE LTD	POLICY NO	: D-21097398MVPC
36 ROBINSON ROAD	OUR REF	: OD 3528
#16-01 CITY HOUSE	VEHICLE NO	: SFP 6883 Z
SINGAPORE 068877	MAKE/MODEL	: TOYOTA COROLLA ALTIS
ATTN: MOTOR CLAIMS DEPT	CHASSIS	: MR053REH104508248
	DATE OF ACCIDENT	: 18.02.22

SURVEY BY

DATE : 19.02.22

1 PC	BONNET <i>bt</i>		S\$	1,248.82
2 PCS	BONNET HINGES	56.90		113.80
1 PC	BONNET WEATHERSTRIP <i>re</i>			47.30
1 PC	BONNET LOCK <i>bt</i>			178.10
1 PC	BONNET INSULATOR <i>de</i>			280.10
1 PC	BONNET STAND STOPPER <i>re</i>			13.70
1 PC	FRONT GRILLE <i>cm</i>			643.10
1 PC	FRONT GRILLE EMBLEM <i>re</i>			25.60
2 PCS	HEADLAMP ASSY <i>cm</i>	2,999.80		5,999.60
1 PC	FRONT BUMPER <i>horn</i>			531.10
2 PCS	FRONT BUMPER SIDE RETAINERS <i>re</i>	85.50		171.00
1 PC	FRONT BUMPER LOWER GRILLE <i>de</i>			170.10
1 PC	FRONT BUMPER REINFORCEMENT <i>bt</i>			399.50
1 PC	FRONT BUMPER SPONGE <i>cm</i>			90.10
2 PCS	FRONT BUMPER BRACKETS <i>re</i>	78.30		156.60
1 PC	FRONT SUPPORT PANEL <i>bt</i>			1,136.30
1 PC	FRONT SUPPORT PANEL TOP GARNISH <i>cm</i>			80.70
1 PC	FRONT BRACE PANEL <i>bt</i>			149.40
2 PCS	HORN <i>sc</i>	120.70		241.40
1 PC	AIR-CON CONDENSER <i>bt</i>			1,801.70
1 PC	AIR-CON SUCTION PIPE <i>?</i>			531.40
2 PCS	AIR-CON LOWER MOUNTING <i>?</i>	37.80		75.60
1 PC	RADIATOR <i>cm</i>			2,148.90
1 PC	RADIATOR FAN MOTOR <i>?</i>			535.50
1 PC	RADIATOR FAN BLADE <i>?</i>			180.40
1 PC	RADIATOR FAN COWLING <i>?</i>			297.20
2 PCS	RADIATOR TOP BRACKET <i>bt</i>	59.70		119.40
1 PC	RADIATOR BY PASS HOSE <i>X</i>			51.78
1 PC	RADIATOR TOP HOSE <i>X</i>			78.90
1 PC	RADIATOR SPARE TANK <i>cm</i>			190.10
1 PC	RADIATOR TOP GARNISH <i>cm</i>			101.00
2 PCS	RADIATOR LOWER BUSH <i>?</i>	23.70		47.40
1 PC	WASHER TANK <i>X</i>			219.10
1 PC	AIR CLEANER BOX <i>cm</i>			1,140.10
1 PC	RESONATOR BOX <i>X</i>			107.00
1 PC	RESONATOR BAX AIR VENT <i>X</i>			191.05
2 PCS	IMPACT SENSOR <i>?</i>	250.00		500.00
1 SET	BATTERY BRACKET <i>bt</i>			36.40
<i>pc</i> 2 PCS	FRONT FENDER <i>LH-repair/RH-bt</i>	908.70		1,817.40
2 PCS	FRONT FENDER INNER SHIELD <i>X</i>	209.10		418.20
2 PCS	FRONT FENDER "VVTI" EMBLEM <i>re</i>	44.17		88.34
2 PCS	FRONT FENDER INNER PANEL <i>repair</i>	440.80		881.60
				S\$ 23,234.79
LESS 25%				5,808.70
				S\$ 17,426.09



進友成汽車服務有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

CON'T FROM PAGE-1

S\$ 17,426.09

1 PC	FRONT WINDSCREEN GLASS <i>cm</i>	S\$ 1,743.60
1 PC	FRONT WINDSCREEN GLASS MOULDING <i>ne</i>	76.00
1 PC	DASHBOARD <i>turn</i>	2,265.00
1 PC	DASHBOARD AIR-BAG <i>act</i>	3,869.30
1 PC	STEERING WHEEL AIR-BAG <i>act</i>	2,867.40
1 PC	STEERING WHEEL AIR-BAG CONTACT PIERE <i>ne</i>	545.90
2 PCS	SAFETY BELT <i>act</i>	995.10
		1,990.20

S\$ 13,357.40

LESS 25%

3,339.35

S\$ 10,018.05

10 PCS	BONNET INSULATOR CLIPS <i>ne</i>	S\$ 30	35.00	S/ NETT
5 PCS	FRONT GRILLE CLIPS <i>ne</i>		20.00	"
10 PCS	FRONT BUMPER CLIPS <i>ne</i>		28.00	"
1 PC	FRONT NUMBER PLATE <i>bt</i>	35	45.00	"
5 PCS	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>ne</i>		18.00	"
1 PC	BATTERY ?		120.00	"
20 PCS	FRONT FENDER INNER SHIELD CLIPS <i>ne</i>	40	60.00	"
1 PC	FRONT WINDSCREEN GLASS SEALANT <i>ne</i>		40.00	"
1 PC	ERP BRACKET <i>ne</i>	20	26.00	"
		S\$	392.00	

TO TOWING CHARGES

S\$ 100.00 ?

TO REMOVE AND RENEW FRONT WINDSCREEN GLASS

140.00 (20)

TO REMOVE AND REFIX DASHBOARD & RELATED WIRE HARDNESS

350.00 200

TO REMOVE AND REPLACE AIR-BAG SYSTEM

250.00 150

TO RE-SET AIR-BAG SYSTEM

250.00 150

TO REMOVE AIR-CON CONDENDER, PIPE, DRIER AND TOP-UP AIR-CON GAS

120.00 60

TO CHECK WIRING FUNCTION

60.00 30

LABOUR CHARGES

1,300.00 1000

TO PUTTY AND SPRAY PAINTING CHARGES

1,500.00 1200 300

S\$ 31,906.14

SIN DOLLARS, THIRTY-ONE THOUSAND NINE HUNDRED SIX AND CENTS FOURTEEN ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul
Hp 90010068
10 days
4s
EXCESS: 500
REVERT
Resurvey after repair