



進友成汽車服務有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No: A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands Industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

MR MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
ATTN: MOTOR CLAIMS DEPT

POLICY NO : D-21097398MVPC
OUR REF : OD 3528
VEHICLE NO : SFP 6883 Z
MAKE/MODEL : TOYOTA COROLLA ALTIS
CHASSIS : MR053REH104508248
DATE OF ACCIDENT : 18.02.22

SURVEY BY

DATE : 19.02.22

1	PC	BONNET <i>bt</i>		SS	1,248.82
2	PCS	BONNET HINGES <i>bt</i>	56.90		113.80
1	PC	BONNET WEATHERSTRIP <i>ne</i>			47.30
1	PC	BONNET LOCK <i>bt</i>			178.10
1	PC	BONNET INSULATOR <i>de</i>			280.10
1	PC	BONNET STAND STOPPER <i>ac</i>			13.70
1	PC	FRONT GRILLE <i>cm</i>			643.10
1	PC	FRONT GRILLE EMBLEM <i>ne</i>			25.60
2	PCS	HEADLAMP ASSY <i>cm</i>	2,999.80		5,999.60
1	PC	FRONT BUMPER <i>cm</i>			531.10
2	PCS	FRONT BUMPER SIDE RETAINERS <i>ne</i>	85.50		171.00
1	PC	FRONT BUMPER LOWER GRILLE <i>de</i>			170.10
1	PC	FRONT BUMPER REINFORCEMENT <i>bt</i>			399.50
1	PC	FRONT BUMPER SPONGE <i>cm</i>			90.10
2	PCS	FRONT BUMPER BRACKETS <i>ne</i>	78.30		156.60
1	PC	FRONT SUPPORT PANEL <i>bt</i>			1,136.30
1	PC	FRONT SUPPORT PANEL TOP GARNISH <i>cm</i>			80.70
1	PC	FRONT BRACE PANEL <i>bt</i>			149.40
2	PCS	HORN <i>sc</i>	120.70		241.40
1	PC	AIR-CON CONDENSER <i>bt</i>			1,801.70
1	PC	AIR-CON SUCTION PIPE <i>bt</i>			531.40
2	PCS	AIR-CON LOWER MOUNTING <i>cm</i>	37.80		75.60
1	PC	RADIATOR <i>cm</i>			2,148.90
1	PC	RADIATOR FAN MOTOR <i>bt</i>			535.50
1	PC	RADIATOR FAN BLADE <i>de</i>			180.40
1	PC	RADIATOR FAN COWLING <i>cm</i>			297.20
2	PCS	RADIATOR TOP BRACKET <i>bt</i>	59.70		119.40
1	PC	RADIATOR BY PASS HOSE <i>cm</i>			51.78
1	PC	RADIATOR TOP HOSE <i>cm</i>			78.90
1	PC	RADIATOR SPARE TANK <i>cm</i>			190.10
1	PC	RADIATOR TOP GARNISH <i>cm</i>			101.00
2	PCS	RADIATOR LOWER BUSH <i>cm</i>	23.70		47.40
1	PC	WASHER TANK <i>cm</i>			219.10
1	PC	AIR CLEANER BOX <i>cm</i>			1,140.10
1	PC	RESONATOR BOX <i>cm</i>			107.00
1	PC	RESONATOR BOX AIR VENT <i>cm</i>			191.05
2	PCS	IMPACT SENSOR <i>cm</i>	250.00		500.00
1	SET	BATTERY BRACKET <i>bt</i>			36.40
1	PCS	FRONT FENDER LH-repair/RH-4 <i>cm</i>	908.70		1,817.40
2	PCS	FRONT FENDER INNER SHIELD <i>cm</i>	209.10		418.20
2	PCS	FRONT FENDER "VTI" EMBLEM <i>cm</i>	44.17		88.34
2	PCS	FRONT FENDER INNER PANEL repair	440.80		881.60
				SS	23,234.79
				LESS 25%	5,808.70
				SS	17,426.09

19802.86
25%
14852.14

908.70

XR



進友成汽車服務有限公司 CYS Automobile Services Pte Ltd

ROC Reg. No. A05041/2001E

GST Reg. NO.: 20-0105041-E

38 Woodlands industrial Park East 1 #07-17 Admiralty Industrial Park Singapore 757700

Tel: 6219 2098 (3 Lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

CON'T FROM PAGE-1

1 PC	FRONT WINDSCREEN GLASS <i>Cmk</i>		S\$	1,743.60
1 PC	FRONT WINDSCREEN GLASS MOULDING <i>Ne</i>			76.00
1 PC	DASHBOARD <i>turn</i>			2,265.00
1 PC	DASHBOARD AIR-BAG <i>ACT</i>			3,869.30
1 PC	STEERING WHEEL AIR-BAG <i>ACT</i>			2,867.40
1 PC	STEERING WHEEL AIR-BAG CONTACT PIERE <i>Ne</i>			545.90
2 PCS	SAFETY BELT <i>ACT</i>	995.10		1,990.20
			S\$	13,357.40
	LESS 25%			3,339.35
			S\$	10,018.05

10 PCS	BONNET INSULATOR CLIPS <i>Ne</i>		S\$	30	38.00	S/ NETT
5 PCS	FRONT GRILLE CLIPS <i>Ne</i>				20.00	"
10 PCS	FRONT BUMPER CLIPS <i>Ne</i>				28.00	"
1 PC	FRONT NUMBER PLATE <i>bt</i>				45.00	"
5 PCS	FRONT SUPPORT PANEL TOP GARNISH CLIPS <i>Ne</i>				18.00	"
1 PC	BATTERY <i>7. Cmk</i>				120.00	"
20 PCS	FRONT FENDER INNER SHIELD CLIPS <i>Ne</i>				60.00	"
1 PC	FRONT WINDSCREEN GLASS SEALANT <i>Ne</i>				40.00	"
1 PC	ERP BRACKET <i>Ne</i>				20	28.00
			S\$		392.00	

TO TOWING CHARGES	S\$	100.00	7X
TO REMOVE AND RENEW FRONT WINDSCREEN GLASS		140.00	120
TO REMOVE AND REFIX DASHBOARD & RELATED WIRE HARDNESS		350.00	200
TO REMOVE AND REPLACE AIR-BAG SYSTEM		250.00	150
TO RE-SET AIR-BAG SYSTEM		250.00	150
TO REMOVE AIR-CON CONDENDER, PIPE, DRIER AND TOP-UP AIR-CON GAS		120.00	60
TO CHECK WIRING FUNCTION		60.00	30
LABOUR CHARGES		1,300.00	1000
TO PUTTY AND SPRAY PAINTING CHARGES		1,500.00	1200 300
	S\$	31,906.14	

SIN DOLLARS, THIRTY-ONE THOUSAND NINE HUNDRED SIX AND CENTS FOURTEEN ONLY

YOUR FAITHFULLY,

CYS AUTOMOBILE SERVICES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

RASUL

#p 50010068

10 days

4S

EXCESS: 500

REVERT

Resurvey after repair