

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC8946H

Make : HYUNDAI

Model : I-40

Date: 21.02.2022

Insurance: NTUC

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRONT BUMPER COVER			\$1,052.20
10	FRONT BUMPER CLIPS			\$22.00
1	FRT BUMPER BRACKET TOP RH			\$44.80
1	RADIATOR GRILLE			\$1,480.00
1	HEADLAMP RH			\$1,388.00
1	HEADLAMP SUPPORT PANEL			\$907.40
1	FRT FENDER RH			\$663.00
	SUB TOTAL		3942.20	\$5,557.40
	LESS 20%			\$1,111.48
	DISCOUNTED TOTAL		3153.76	\$4,445.92
	FRT NUMBER PLATE WITH TRIM COVER			\$55.00
			49.50	\$55.00
	Labour Charge			
	PANEL BEATING			\$900.00
	SPRAY PAINTING CHARGE			\$600.00
	TUFF KOTE			\$60.00
	CHK ALL LIGHTING			\$60.00
			6055	\$1,620.00
	TOTAL LABOUR		4258.26	
	ESTIMATE TOTAL		6153.400	\$6,120.92
			02 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanpin 97495745
 up 21/2/22 0445
 4/5 Resurvey after repair
 Tanpin 01/04/2022
 2-3 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: